


RELAY CODES & COMPONENTS LIST, **GBW 16560**  
 2280 CYCLES PER SECOND RECEIVER  
 N.Z. SIGNALLING SYSTEMS A.C. Nos. 2T & 3T

RELAY	B.C.C. CODE	DIAG. FIG.	NOTES	COMPT. DESIGNATION	B.P.O. CODE	NOTES
				R1, R6	26 KC	
				R7, R9		
				R14, R23		
			NO RELAYS	R2, R5	26 KD	
				R8, R10		
				R3,	WELWYN MR5	
				R11-R13		OR
				R15-R20	ELECTROSIL TR5	
				R4	RESISTOR 35	
				R21	LWYN MR8	
				R22		OR ELECTROSIL TR8
				C1	121G	AEI CODE
				C2	TS.A. 1410 GRP. 84	AEI CODE
				C3, C4	42 F.U.	AEI CODE
				MR1	QB/3	STC CODE NOTE C1.
				MR2-8		MULLARD AAZ15 OR EQUIV.
				MR12		NOTE C2
				MR9-11	1S 131	TEXAS INSTRUMENTS
				MR13	1S 131	TEXAS INSTRUMENTS
				T1	413 A	AEI CODE
				T2	414 A	AEI CODE
				RV1	404/1100062/473/A	PLESSEY CODE
				RV2	T38153B	AEI CODE
				PLATE ASSEM. T34255		AEI CODE
				VT1, 3&5	CV 7438 OR EQUIV.	
				VT4	CV 7363 OR EQUIV.	
AEI UNIT ASSEMBLY:-						
PRINTED WRG. UNIT	45C	PRO-ELECTRON TRANSISTORS				

NOTES:- A. SPECIAL FACTORS OF SAFETY B. SPECIAL ADJUSTMENTS C. CCT. POINTS OR MODIFICATIONS.



NOTE C1: SOME EARLY EQUIPMENT MAY HAVE MR1 AS QB/5  
 C2: ON SOME EARLY EQUIPMENT MR2 WAS CG 85-H. MR3-8 WERE CG83-H. MR12 WAS CG81-H

NZPO  
 (13313)  
 5.6.70

ISSUE 5 APP REDRAWN SHEET 2 ADDED	ISSUE 6 WIRING COLOURS AMENDED.	ISSUE 7 2.7.3-66 COMPT CODES AMENDED. RV2 WAS T34161 & PLATE ASSEM. WAS T34251	ISSUE 8 15-7-68 NZPO NOTE A ADDED (8404) DLM	ISS 8A 27.4.74 MR1 WAS QB/5 NOTE C1 WAS NOT SHOWN. VT1-VT3 & VT5 WERE ACY20-VT4 WAS DCZ11-NZ NOTE A DELETED (3972) DLM	ISS 9 2.11.70 MR2 WAS CG85-H MR3-8 WERE 2563-H MR13 WAS CG81-H (3972) DLM	ISSUE 10 27.6.71
--	---------------------------------------	--	---	--	---	------------------

ORIGINATED BY	AEI
DATE	30/10/63
SIGNED FOR COMMITTEE	ASH JOK

RELAY CODES & COMPONENTS LIST, **GBW** 16560


2280 CYCLES PER SECOND RECEIVER

N.Z. SIGNALLING SYSTEMS A.C. Nos 2T & 3T

RELAY	B.C.C. CODE	DIAG. FIG.	NOTES	COMPT. DESIGNATION	BPO CODE	NOTES
				VT6	CV7376 OR EQUIV.	MÜLLARD CODE
				LI	COIL CHOKE 68A	A.E.I. CODE

NOTES: - A. SPECIAL FACTORS OF SAFETY. B. SPECIAL ADJUSTMENTS. C. CCT. POINTS OR MODIFICATIONS

LAYOUT.  
PRINTED WIRING VIEWED FROM EQUIPMENT SIDE



ISSUE 1 SHEET 2 ADDED	ISSUE 6 2A-8-65 NO CHANGE	ISSUE 7 22-3-66 VT6 & LI ADDED IN CODE COLUMN.	ISSUE 8 15-7-68 NO CHANGE SHEET AMENDED (8404)	ISS 8A: 27.4.71 VT6 WAS ACY 17 (39726)	ISS 9: 2-1-70	ISS. ADVANCED WITHOUT CHANGE (39726)	ISS 10: 27-8-71	NZ.P.O. (13313) 5-6-70	ORIGINATED BY A.E.I.	DATE 24/8/65	SIGNED FOR COMMITTEE Ash
--------------------------	---------------------------------	--	--	--	---------------	--	-----------------	------------------------------	-------------------------	-----------------	-----------------------------

5  
10  
15  
20  
25  
30