FIG.3
SWITCHING KEY
LOCATED EXTERNAL TO EXCHANGE



FIG.4
SWITCHING KEY
LOCATED TO SUIT LOCAL CONDITIONS



FIG.1 C.T.S.
SWITCHING KEY



FIG.2 M.A.R.
SWITCHING EQUIPMENT FOR LAMP RELAYS



NOTES:-

1. FUSE:- FIG.2 1·5A PER 50 RELAYS
2. EACH SPRING SET OF KS TO SERVE 50 RELAYS (MAX.)
3. ALL WIRING TO BE 25 SWG UNLESS OTHERWISE SPECIFIED.

AMENDMENT PARTICULARS	ISSUE	DATE	APP'D
(58280)	1	10.2.67	GJB

CONCENTRATION AND BUSYING CIRCUIT (GEO-THERMAL AREAS)

N.Z.P.O. | DRAWN | CHECKED | WIRING | CIRCUIT | SIZE: S | GBW 19200 | REF:- GS 3-11-11 (GBW 12710) | 50% | E