SHEET 1 OF 1

RELAY CODES & COMPONENTS LIST, GBW 12390

MANUAL BOARD ADAPTOR CCT FOR B/W 2V.F. TOLL LINE

SIEMENS Nº16 EXCHANGES

RELAY	B.C.C. CODE	DIAG. FIG.	NOTES
BR	1618		
D	5795		B
DL	5794		
IB	6001		
IC	6297		
LR	60166		
RA	2012		
RF	5793		A
S	5792		

COMPT DESIGNATION	BPO CODE	NOTES
R1, R2	Nº9	
R3, R4	Nº12	
R6	Nº15 GD	R6 MOUNTED ON C1
R7		R7 MOUNTED ON C2
C1, C2, C3	103	
MR1	2/6AZ	

NOTES:- A. SPECIAL FACTORS OF SAFETY. B. SPECIAL ADJUSTMENTS. C. CCT. POINTS OR MODIFICATIONS

LAYOUT.

R1/R2	R3/R4	C1 (R6)	C2 (R7)	C3	-	-	-	-	-
BR	D	DL	IB	IC	LR	RF	S	RA	MR1

CANCELLED

ISSUE 1 22-1-63 RELEVANT CIRCUIT CANCELLED (53403)	ISSUE 2 2-5-66	APP.

ORIGINATED BY	A.E.I.
DATE	22-1-63
SIGNED FOR COMMITTEE	