GBW 15870

RELAY CODES & COMPONENTS LIST

MULTIPLE JACKS WITH VE'S 6V AC SUPPLY AUCKLAND AUXILIARY TOLL EXCHANGE.

RELAY	BCA CODE	DIAG. FIG	NOTES
VE	749	3	

COMPT. DESIG-NATION	BPO CODE	NOTES

NOTES A SPECIAL FACTORS OF SAFETY B SPECIAL ADJUSTMENTS C CCT P[illegible]NTS OF MODIFICATIONS.

LAYOUT



APP	ORIGINATED BY	G.E.C.
ISSUE 1 23-6-60	DATE	23-6-60
	SIGNED FOR COMMITTEE	