RELAY CODES & COMPONENTS LIST, GBW 16490

DEPENDENT EXCHANGE O/G LINE CIRCUIT FOR BOTHWAY JUNCTIONS (FOR USE WITH F/C LINE CIRCUIT) TO PARENT EXCHANGE

N.Z.S.S.A.C. No. 3T

RELAY	B.C.C. CODE	DIAG FIG	NOTES
A	HSD 702	1A	
AA	HSD 701	1A	
AK	5953	1B	
B	13931	1B	
BB	50183	1B	
BR	50211	1B	
CB	6383	1A	
CD	50212	1B	
CF	50198	1B	
CH	5957	1A	
D	50213	1A	
DB	1075	1B	
DC	5959	1A	
DD	5960	1A	
DX	5961 P	1B	C
LA	7083	1A	

COMPT DESIGNATION	BPO CODE	NOTES
R1-9	9	
R10	6	MTD ON C1
R11-12	12	
R13-14	15	NON-INDUCTIVE.
R15-16	15A	NON-INDUCTIVE
C1	T204 MK 2	
C2A &B	MC 103C MK 2	
C3	102C	
R18-20	15	NON-INDUCTIVE
MR1-3	DA 000	JOSEPH LUCAS CODE MTD IN WIRING
RV1	26E	
RX1-8	2	MTD IN WIRING
T1	415A	A.E.I. CODE.
T.C.F.T.1	CLEAR FORWARD	A.E.I. UNIT CODE
	TIMER GBW16710	UNIT. ELECTRONIC 20A.

NOTES: A. SPECIAL FACTORS OF SAFETY. B. SPECIAL ADJUSTMENTS. C. [illegible] POINTS OR ANDEREN WITH MS.

LAYOUT
PART 1

C:- WDGS CONNECTED DIFFERENTIALLY.

ϕ GUARD 1.

FRONT VIEW

R1/2/3	
	T1
AA	SP
A	SS
D	DD
MH	CH
WA	CB
LB	WB
LA	WS

REAR VIEW (BOXES OPEN)

C3

HINGES.

R4 R7

R11 R12 R15 R16

1 LABEL HOLDER No. 14.
2 PLUGS 32 Pt. P.O. 3205 NO JACKS TEST ETC.

ISSUE	APP	DETAILS
ISSUE 1 19-3-65 NO CHANGE		
ISSUE 2 17-5-65		CAPACITOR BOX LAYOUT & TITLE AMENDED
ISSUE 3 17.9.65.		R17 DELETED RV1 & RX6-8 ADDED (83701)
ISSUE 4 22.5.67.		

ORIGINATED BY	A.E.I
DATE	19.3.65
SIGNED FOR COMMITTEE	ASH

NZPO (58280) 10-2-67

RELAY CODES & COMPONENTS LIST, GBW 16490

DEPENDENT EXCHANGE O/G LINE CIRCUIT FOR BOTHWAY JUNCTIONS (FOR USE WITH I/S LINE CIRCUIT) TO PARENT EXCHANGE N.Z.S.S. A.C. No 31.

RELAY	B.C.C. CODE	DIAG. FIG.	NOTES
LB	5962	1A	
MH	10421	1A	
RG	50202	1B	
RL	5963	1B	
SA	50214 Pd	1B	
SB	4539	1B	
SP	HSD 508	1A	
SR	5942	1B	
SS	5965	1A	
TX	HSD 512	1B	
WA	5966	1A	
WB	50215	1A	
WS	5968	1A	

COMPT DESIGNATION	BPO CODE	NOTES

NOTES:- A. SPECIAL FACTORS OF SAFETY B. SPECIAL ADJUSTMENTS C. CCT. POINTS OR MODIFICATION

LAYOUT.

PART 2.

FRONT VIEW

	RG/8/9	RVI	*
	BR	RL	
ø	B	BB	ø
	CD	SA	
	SR	DC	
	CF	DX	
	DB	TX	
ø	RG	SB	ø
	T.C.F.T.I	AK	

REAR VIEW (BOXES OPEN)



ø GUARD 1

* RVI MOUNTED ON P.O. BRACKET MTG. CV.

+ LOCKING NUT P.O. SPINDLE LOCK No 1.

2 PLUGS 32 Pt P.O. 3205
1 P.O. JACK TEST 21E MK 2
1 P.O. JACK TEST 21F MK 2
1 LINK P.O. N' RED

APP	ISSUE 1	ISSUE 2	ISSUE 3	ISSUE 4
	19-3-65 LINK P.O. N' RED W/AS LINK P.O. No 6	17-5-65 CAPACITOR BOX LAYOUTS ON BOTH SHEETS AMENDED	17-9-65 R17 DELETED RVI ADDED (8310)	22.5.67.

ORIGINATED BY	A.E.I.
DATE	19.3.65
SIGNED FOR COMMITTEE	

NZPO (58861) 10.2.67