SHEET 1 OF 1

RELAY CODES & COMPONENTS LIST GBW16940

O/G TO AUTO W/- SENDER HUNTER

INTERNATIONAL EXCHANGE

RELAY	B.C.C. CODE	DIAG FIG.	NOTES
S	5878		B
LF	1005		
SS	70743		
TR	1478A		B
K	6417		
IL	2012		
LR	13066		
I	2022		
LC	2017		
ST	15911		
D	16472		B
KA	16168		
M	16167		
RR	6203		B
SD	6114		B

COMPT DESIGNATION	B.P.O. CODE	NOTES
R1A, R1B	9	MOUNTED IN CAPACITOR BOX N.Z. NOTE A.
R2A, R2B	9	
R3	12	
R4	26GD	
R5	12	
(R6)	6	
C1 C2	103C/2	
C3	102C/2	
C4	101/2	
MR1-4		DIODE DA000
TJ	21F/4 & 21E/4	6PT & 8PT FIG 3.
SH	2	8 LEVEL U/S
R7	9	
R8	12	
R9	12	
MR5		DIODE HS1009 OR EQUIV.
MR6		" " " " "
MR7		" " " " "

NOTES:- A SPECIAL FACTORS OF SAFETY B SPECIAL ADJUSTMENTS
C. CIRCUIT POINTS OR MODIFICATIONS

LAYOUT

FIG. 2

RELAY SET

S	R2A/2B/3
LF	LC
(6D) SS	ST
TR	D
K	KA
IL	M
LR	RR
I	SD

APP	R.C.	R.C.	R.C.	ORIGINATED BY RK	A.T.&E. Co.
ISSUE 1	REL.5D. ADDED REL.6 WAS 10221. REL.5S. WAS 7939. R7,8&9, MR5, MR6/7 ADDED REL D WAS 91418 ISSUE 2. 23-12-69	N.Z. NOTE A ADDED AND CODES OF RELS. TR & IL CHANGED ISSUE 2A 11-5-70 (13672)	R1 CHANGED TO R1A & R1B R2 CHANGED TO R2A & R2B R1A & R1B MTD. IN CAPACITOR BOX. N.Z. NOTE A DELETED. ISSUE 3 2-10-70 (13805)	DATE	15-10-68
				SIGNED FOR COMMITTEE	A. Aston

A.T.E. 1960 REV. E451