



NOTES:-

- FUSING: FIG. 1 1-5A PER RELAY SET (5 CIRCUITS) FIG. 1A 1-5A PER CIRCUIT. FIG. 2 1-5A PER CIRCUIT.
- WHEN ALLOTTER IS NOT FITTED OMIT CONNECTIONS SHOWN & ADD CONNECTIONS SHOWN
- THE FOLLOWING JACK POINTS (FIG. 1) TO MAKE CONTACT WHEN RELAY SET IS REMOVED:- U2 & 4, U6 & 8, U9 & 11, U17 & 19, U21 & 23, U30 & 32
- JACK POINTS U9 & 11 (FIG. 2) TO MAKE CONTACT WHEN RELAY SET IS REMOVED.
- WHEN 50 POINT FINDER IS PROVIDED ROWS 5, 6, 7 & 8 ARE CONNECTED TO OUTLETS ASSOCIATED WITH EVEN NUMBERED WIPERS.
- FINDER BANK MULT STRIP CONN TO BE STRAPPED TO GIVE REPEATED APPEARANCES OF SUBS. TAPPING RELAYS UNTIL ALL OUTLETS ARE USED
- ALLOTTER BANK WIRING TO GIVE REPEAT APPEARANCE OF THE LINE FINDER RELAY SET EVERY 12TH CONTACT FOR GROUPS OF 6 OR LESS APPEARANCE TO BE REPEATED EVERY 6TH CONTACT. OUTLETS NOT CONNECTED TO LINE FINDERS TO BE EARTHED ON BANK D1
- ALL WIRING TO BE 0.5mm UNLESS OTHERWISE SPECIFIED.
- FOR WIRING SEE GBW 10870 OR EQUIV.
- P LEAD NOT REQD WHEN CIRCUIT IS DIRECTLY CONNECTED TO MANUAL BOARD RELAY SET.

AMENDMENT PARTICULARS		ISSUE	DATE	APPRO	REF. SEC. DRG. SB302	SIZE S	50V	E
MOD TO FIG. 2 LB2 & ETH. RUN (38307)	E	14-7-83	JR					
LB RELAY AMD. (192772)	D	16-4-80	RED					
RC & LB RELAYS CHANGED NZMRT METRICATED (193403)	C	5-5-78	RED					
NZPO MOD CODED CGAND MINOR CORRECTIONS(4392)	B	18-5-77	RED					
PREP FROM GBW 10720 155 4 OF 10-8-62 (154291)	A	10-11-76	RED					

CHANGED NUMBER CALLING EQUIPT. TAPPING CIRCUIT & LINE FINDER.

GBW 10720 MODA