


EXPLANATORY ONLY
MANUAL BOARD.




NOTES.

1. FUSE 1.5 AMP PER RELAY SET, 2 CIRCUITS.
2. Ø FOR WIRING SEE G.B.W 10640 OR EQUIVALENT.

ETH. ETH. BAR 0.9mmR (A) U11
BATT FUSE 0.9mm BK (B) U12

ETH. R. U11 - LC1 - Sd - S1 - SR23 - SR1 - SR3 - Sd - S1 - LC1 - Ib - Ie
LL4 - SS4 - SR23 - SR1 - SR3 - SS4 - LL4 - Ib - Ie.
BATT. BK. U12 - SRe - LLe - SSe - SRe - SSe - LLe - YA2 - YB2 - YA2 - YB2.



		SLOW RELEASE		SLOW OPERATE	
LEVEL 0 JUNCTION RELAY SET SLEEVE CONTROL MANUAL BD 2000 TYPE.					
RETRACED & METRICATED		(154588)	IA	10-5-78	RED
		(7911)	I	15-7-53	
AMENDMENT PARTICULARS.			ISSUE DATE	APPD	SIZE S 50V S
NZPO		DRAWN CHECKED WIRING CIRCUIT		GBW 12010	