



- NOTES**
1. FUSE = 1.0A PER CIRCUIT.
 2. ⓪ FOR WIRING SEE GBW 13730 OR EQUIV.
 3. ALL WIRING TO BE 25 SWG UNLESS OTHERWISE SPECIFIED.
 4. UNLESS OTHERWISE SPECIFIED ALL TERMINALS ARE ON STRIP CONN. AT REAR AND ARE DESIGNATED 'SC' IN WIRING RUNS.
 5. RELAY 'OC' IS DIFFERENTIALLY CONNECTED.
 6. WHEN JUNCTION RESISTANCE EXCEEDS 200 OHMS STRAP TERMINALS 32 & 42.
 7. WHEN METERING IS NOT PROVIDED DELETE WIRING SHOWN THUS —|—|—

FOR USE IN LIEU OF GBW16831

| | | | |
|---|--------------|------------------|--------------|
| □ | SLOW RELEASE | ⊗ | SLOW OPERATE |
| UAX N°NZ 13 OUTGOING JUNCTION TO DEPENDENT UAX (TERMINAL TRAFFIC ONLY) | | | |
| PREPARED FROM GBW 13950 ISS 5A. (6/200) | | A 3-11-75 CJW | |
| AMENDMENT PARTICULARS | | ISSUE DATE / APD | |
| SIZE L | | 30V/H | |
| GBW 13950 MOD C | | | |

NZPO _____ DRAWN _____ CHECKED _____ WIRING _____ CIRCUIT _____