



NOTES

- 1. FUSING 1-5A PER CIRCUIT.
- 2. ALL WIRING TO BE 25 SWG UNLESS OTHERWISE SPEC'D.
- 3. JACK POINTS 9 & 11 TO MAKE CONTACT WHEN RELAY SET IS REMOVED.
- 4. STRAP U14-27 WHEN REPEAT METERING EQUIPMENT IS NOT PROVIDED.
- 5. Ø FOR WIRING SEE GBW10640 OR EQUIV.

BATT BK 22 SWG FUSE (16) U12
 ETH R 22 SWG ETH BAR (1A) U11
 BATT W U12-5Ae-De-MBa-MBc-MAb-MAc-
 MRc-MMe-GHe-De-ZMe-SCc-MCb-
 MCc-SBc-PRc-R3b-R2b-R1b
 EARTH R U11-D1-M1-DB24-DAc-MMj1-CH22-
 CH24-CH26-ZM1-CO2-SC1-PR22-R5a-TJ1

SUPERSEDED BY GBW 14361

AMENDMENT PARTICULARS	ISSUE DATE	APPRO.
TNA LEAD FROM U22 DELETED (66897)	3-9-52	
TJ3&4 RECONNECTED TJS 13,14 WERE SPARE (10572)	2-14-58	
	8-9-55	

5 SLOW RELEASE 5 SLOW OPERAT

MULTI FREEM RELAY SET
CONNECTED OFF D.S.R. LEVELS

SIZE: M 50V

GBW 14360

N.Z.P.O. DRAWN: J.N.I. CHECKED: W.I.R. WIRING: C.I.R. CIRCUIT: Dae