


0
5 Centimetres
10
15
20
25
30



NOTES:-

1. FUSING 1.0A/CCT.
2. TO INCREASE SENSITIVITY TO RINGING WHEN USED ON LINES OF VERY HIGH RESISTANCE STRAP UPTS 3 & 7.
3. ALL WIRING TO BE 25 SWG UNLESS OTHERWISE SPECIFIED.
4. Ø FOR WIRING SEE RACK COMMON SERVICES DIAGRAM.

BATT. W. U12 - SR e - RRE - R1 b.

BATT. BK. FUSE. 22 SWG. 3B U12

ETH. R. U11 - T1/E - LRI - LS2 - RR3.

EARTH R. ETH. BAR. 22 SWG. 3A U11

TJ
2

				GENERATOR SIGNALLING REPEATER RELAY SET	
				SIZE: S	50v W
				GBW 15310	
N.Z.P.O.	DRAWN TU	CHECKED	WIRING	CIRCUIT S.C.R.	
			ISSUE	DATE	APPD
			1	29.12.58	Dr.
			2	8-9-61	Dr.
			LS1 WAS MAKE CONTACT (42254) (17576)		