



**T.A.R.I. N.Z.S.S. A.C. No. 21 & 31 RECEIVER**  
SEE GBW 16560 OR EQUIV.

**NOTES**

1. FUSING 1.5A PER CIRCUIT AND T.A.R.I. (GBW 16560)
2. WHEN THE CIRCUIT IS USED ONLY U-POINTS 3 & 11 IS & 20, 21 & 23, 22 & 24, 25 & 27, 26 & 28 AND 30 & 32 TO BE STRAPPED EXTERNALLY.
3. THESE TERMINALS ARE STRAPPED AS REQUIRED DURING THE RECEIVER SET UP PROCEDURE. FOR DETAILS SEE GBW 16560.
4. SHELF JACK POINTS U9 & U11 TO MAKE CONTACT WHEN RELAY SET IS REMOVED.
5. WHEN THIS CIRCUIT IS USED ON A BOWWAY LINE U-POINTS 11, 18, 20, 21, 23, 25, 26, 27, 28, 30, 31 & 32 TO BE STRAPPED TO THE SIMILARLY NUMBERED U-POINTS OF THE ASSOCIATED O/C CIRCUIT (GBW 16490 PART 2 OR EQUIV.) U-POINT 24 TO BE STRAPPED TO ASSOCIATED U-POINT OF GBW 16490 PART 1 U-POINT 3 TO BE STRAPPED TO U-POINT 13 OF GBW 16490 PART 2.
6. FOR WIRING SEE GBW 12110 OR GBW 13730 OR EQUIV.
7. ALL WIRING NOT OTHERWISE SPECIFIED TO BE 2S SWG.
8. ON EARLIER EQUIPMENT COLOUR OF BATTERY WIRING WAS BK OR W.

**NOTE 8**

- BATT. 22 SWG V FUSE 5B2 U12
- ETH. 22 SWG R ETH 5A2 U11 (NOTE 2)
- BATT. V U12-R4b-R5b-X2-Ae-C0e-DAe-Twe-R5e-R6e-CRe-TRe-De-RRe-AKe-DRb-De-TAR/1/3-SCA2
- ETH. R U11-X22-R23-BR28-BRC BR3-CD3-DA21-TW1-R51-RP22-CR24-RR21-RR2-D21-T2/5C-TVE-TAR/1/4-SCA1-R7e

NZPO						
DRAWN	CHECKED	WIRING	CIRCUIT			
ISSUE	DATE	REF.	DATE	ISSUE	DATE	REF.
GBW 16520						