



- NOTES.**
- FUSING: - 1.5A FOR FIG. 1.
1.5A FOR FIGS. 2, 3 & 4.
 - ALL WIRING TO BE 0.5mm UNLESS OTHERWISE SPECIFIED
 - RESISTOR R1 TO CONSIST OF 5 RESISTORS THUS:-
R1A 50Ω, R1B 100Ω, R1C 200Ω, R1D 400Ω, R1E 800Ω. THE RESISTORS TO BE WIRED IN SERIES INITIALLY. RESISTANCE TO BE ADJUSTED ON SITE TO SET IMPULSE SPEED READING.
 - WHEN RURAL LINE TEST FACILITIES ARE SPECIFIED, PROVIDE FIG. 4 AND CONNECTIONS SHOWN -1-1- AND OMIT CONNECTIONS SHOWN -2-2-.

