

FIG. A. EXCHANGES WITHOUT I.D.F.

				FAULTSMENS LINES TERMINATING ON TEST DESK OR RACK OR FAULT DISPATCHING POSITION OR EQUIV WITH TONE SWITCHING KEY (GEO-THERMAL AREAS)	
REFS. TO TEST RACK ADDED	(8004)	2	19.3.71	B.S.H.	
	(58281)	1	9.2.67	478	
AMENDMENT PARTICULARS		ISSUE	DATE	APPD	E
				GBX 19030	
N.Z.P.O.	DRAWN	CHECKED	WIRING	CIRCUIT	SHEET 1-3




FIG.B. EXCHANGES WITH IDF

				FAULTSMEN'S LINES TERMINATING ON TEST DESK OR RACK OR FAULT DISPATCHING POSITION OR EQUIV. WITH TONE SWITCHING KEY (GEO-THERMAL AREAS)	
REFS TO TASK RACK ADDED	(8004)	2	19.3.71	B5H.	
	(58281)	1	9.2.67	A/B.	
AMENDMENT PARTICULARS		ISSUE DATE		APPD.	
N.Z.P.O.		DRAWN	CHECKED	WIRING	CIRCUIT
				GBX 19030	
				SHEET 2-3	




FIG. C. EXCHANGES USING T.D.F. & I.D.F.

REFS. TO TEST RACK ADDED	(8001)	2	19.3.71	85H.
	(58281)	1	9.2.67	013
AMENDMENT PARTICULARS		ISSUE	DATE	APPD
N.Z.P.O.	DRAWN	CHECKED	WIRING	CIRCUIT

FAULTSMEN'S LINES
 TERMINATING ON TEST DESK OR RACK OR
 FAULT DISPATCHING POSITION
 OR EQUIV
 WITH TONE SWITCHING KEY
 (GEO-THERMAL AREAS)

GBX 19030

SHEET 3-3