


ROUTINER FOR GROUP SELECTORS  
WITHOUT BUSY FLASH TO GBW 10760. TEST UNIT  
2000 TYPE.


RELAY	BCC CODE	DIAG. FIG	NOTES	COMPT. DESIGNATION	BPO CODE	NOTES
A	6119			R1,5,6	Nº 6	
AE	20517		SPRINGS 25/26 SPARE & UNWIRED.	R2-4	Nº 9	
AO	1005			R10-12		
AR	20489			R14,15	Nº 9A	
B	4365			R8,13		
BA	5722		SPRINGS 23/24 SPARE & UNWIRED	R7,9 =	Nº 12	
BB	5722		SPRINGS 23/24 SPARE & UNWIRED	R16-21		
BI	7175		ALTERNATIVE CODES.	R24,25	Nº 12A	
BI	20491	FIG.3.				R22,23
BT	40695 Pd			C1,2,3	Nº 101	
CF	4073			C4	Nº 102	
CQ	6197		SPGS 7/8/9 & 23/24/25 SPARE & UNWIRED.	MR1, 7	4/6AZ	
DE	5723			MR2	1/12AZ	
DR	20519		SPRING. 5 SPARE & UNWIRED.	MR3-6	2N/6AZ.	
DS	4295			U/S'S	2/87AN.	
DU	1423			U/S'T	2/87AN.	
				RX1	RESISTOR NON-LINEAR	MOUNTED ON RELAY BT
				R26	Nº 9	
				R27	Nº 9	
				D1		IN4003
				D2		IN4003 (Mounted on
				D3		IN4003 (rear of RC)

NOTES A SPECIAL FACTORS OF SAFETY B SPECIAL ADJUSTMENTS C CCT POINTS OF MODIFICATIONS.



ISSUE 1 17-4-70	APP	ORIGINATED BY REC/AE1
BT RELAY CODE CHANGED RX4 ADDED (122712) KG		DATE 17-4-70
ISSUE 1A. 17-7-74		SIGNED FOR COMMITTEE R.I.J.
R26, R27, D123 ADDED. (199576)		
ISSUE 1B 20-12-78 WAH		
NO CHANGE. (38437) FB		
ISSUE 1C 4-10-85		

ROUTINER FOR GROUP SELECTORS  
WITHOUT BUSY FLASH TO GBW 10760 TEST UNIT  
2000 TYPE



RELAY	BCC CODE	DIAG FIG	NOTES	COMPT. DESIGNATION	BPO CODE	NOTES
DV	1618			KNFI/KPFI	Nº 2,12	
				KIC/K2C		
GQ	6197		SPGS 7/8/9 & 23/24/25 SPARE AND UNWIRED	KBFI	Nº 68	
H	1816		1/2/3, 26/27/28/29 SPARE AND UNWIRED	KBT		
IP	2017			LPI-32	Nº 2/6V	
IQ	10313P					
IR	10313P					
LA	10322		SPRINGS 1/2 SPARE AND UNWIRED			
LB	10322		SPRINGS 1/2 SPARE & UNWIRED			
LC	1425					
LD	1425					
LI	20507					
LT	5815					
NL	10068		SPGS 3/4 SPARE & UNWIRED			
			TEST AND RA. FIG'S			
PA	45521		TEST AND RA. FIGS			
PB	2318		SPGS 23/24/25 26/27/28/29 SPARE & UNWIRED			
PE	5816					

NOTES: A: SPECIAL FACTORS OF SAFETY B: SPECIAL ADJUSTMENTS C: CCT POINTS OF MODIFICATION

LAYOUT




FIG 2

ISSUE 1	APP	KG	ISSUE 1B 20-12-78	WAB	ORIGIN:	GEC/AE1
17-4-70	NO CHANGE		NO CHANGE	SHT 4 AMD (38437) FB	DATE:	17-4-70
ISS 1A	16-7-74		ISSUE 1C 4-10-83		SIGNED:	R.I.J.
R26,27 ADDED	(122712)					

RELAY CODES & COMPONENTS LIST

GBW 11221

ROUTINER FOR GROUP SELECTORS  
WITHOUT BUSY FLASH TO GBW 10760 TEST UNIT  
2000 TYPE.

RELAY	BCC CODE	DIAG. FIG	NOTES	COMPT. DESIGNATION	BPO. CODE	NOTES
PF	10137					
PG	20521		SPRINGS 3/4, 21/22 SPARE & UNWIRED.			
PH	7288					
PL	10068		SPGS 3/4 SPARE & UNWIRED TEST & RA FIGURES			
PT	H5522		TEST & RA FIGURES.			
PTA	HSD740		TEST & RA FIGURES			
PW	5423.					
PX	20522		SPRING 7 SPARE & UNWIRED.			
PY	20523					
PZ	20524		SPRINGS 21/22 SPARE & UNWIRED.			
RT	1709		SPRING 25 SPARE & UNWIRED.			
SG	10147		SPRINGS 21/22 SPARE & UNWIRED.			
SS	10146					
SZ	20525					
TA	H5521					
TD	4031					

NOTES A SPECIAL FACTORS OF SAFETY B SPECIAL ADJUSTMENTS C CCT POINTS OF MODIFICATIONS.

START	SEL BUSY	CALL TRAP BUSY	1ST TL BUSY	2ND TL BUSY	1/C LINES	GUARD	A REL RLSE	A REL OP	RLSE TIMING
⊗									⊗
IMP. MON KEY LINES	C REL ROT HUNT	1ST TL SEIZED	2ND TL WIFERS DIS	O/G LINES	RLSE GUARD	IMP LEAKY LINE	C REL ROT HUNT	2ND TL SEIZED	1ST TL WIFERS DIS.
⊗									⊗
O/G LINES	RLSE GUARD	IMP LEAKY LINE	BUSY RECD	OM ETH	RLSE GUARD				TEST FIN.
⊗									⊗
NEG LINE FAULT	Pos LINE FAULT	PRV GUARD FAIL	RLSE FAST	RLSE SLOW.					⊗
⊗									⊗
TEST CONTROL									
KNFI		KIC							
+	+	+	+						
KPFI	KBFI	KZC	KBT						

FIG.3.



ISSUE 1. 17-4-70	ADPT KG	NO CHANGE SHT LAMD (122712)	ISSUE 1A 17-774	NO CHANGE (193576)	ISS 1B 20-12-78 WAH	NO CHANGE. SHT 4 AMD(38437) FB	ISS.1C 4-10-83
---------------------	------------	-----------------------------------	--------------------	-----------------------	---------------------	-----------------------------------	----------------

ORIGINATED BY	GEC/AEI
DATE	17-4-70.
SIGNED FOR COMMITTEE	R.I.J.

N.Z.P.O  
(13686) 5-6-70

