


RELAY CODES & COMPONENTS LIST, GBW 12270  
 INTERWORKING REGISTER TYPE SR.3 S/S TO ROTARY  
 3 SELECTION (ODD HUNDREDS PAIRED WITH NEXT HIGHEST DIGIT)


RELAY	BCC CODE	DIA FIG	NOTES	COMPT. DESIGNATION	BPO CODE	NOTES
CC	40857 PL			R1 to R4	6	
CO	7499			R5 to R7	12	
CT	1108			R8	9	
CU	4650			C1 to C4	MC101	
HO	10090					
IC	4691			RX1	PO No 2	NON-LINEAR RESISTORS
JH	4742		B	RX2	" "	" "
JHS	20119			RX3	" "	" "
K	40855 PL			MRI	1/12A	
MO	2564			SS	2/8/13AN	
OS B	HS 714		HS 510 IS USED ON EARLY JOBS	CR	2/42AN	
PR	4647			DR		
SR	40858 PL			UR		
TA	4652			KFL	68	
TG	4651			KHO	236	
TR	40853 PL			LPI	4008A LAMP	S.T.C. CODE
				LP2	SOCKET	
				DI-D3	-	IN 4003 MOTOROLA, I.T.T OR TEXAS INSTRUMENTS

NOTES - A SPECIAL FACTORS OF SAFETY. B SPECIAL ADJUSTMENTS. C CCT. POINTS OR MODIFICATIONS.

LAYOUT



FRONT VIEW




CAPACITOR BOX

N.Z.P.O. (122840) 29.3.74. JHE

ISSUE 1/16.4.52 APP  
 WAS C.R.D.S.  
 OS WAS HS510  
 1552  
 DI-D3 & R8  
 ADDED  
 1553  
 CC WAS 4643  
 K " 4653P  
 SR " 4693  
 TR " 4750  
 RX1 & 2 DELETED  
 C5, C6, R9, R10  
 RX3 ADDED  
 1554  
 1973  
 RX1 & RX2  
 REINSTATED  
 C5 & C6, R9  
 R10 DELETED  
 1555

ORIGINATED BY	S.T.C.
DATE	16-4-52
SIGNED FOR COMMITTEE	<i>[Signature]</i>




# RELAY CODES & COMPONENTS LIST, GBW 12270

## INTERWORKING REGISTER

RELAY	BCC CODE	DIAG FIG	NOTES	COMPT DESIGNATION	BPO CODE	NOTES
TS	4748					

NOTES - A SPECIAL FACTORS OF SAFETY. B SPECIAL ADJUSTMENTS. C CCT. POINTS OR MODIFICATIONS.

### LAYOUT



N.Z.P.O.  
(122840) 29.3.74. JHE

ISSUE 1 - 16.4.52 ADW  
 WAS CARDS  
 1552 SHTY CHANGED  
 1553 SHT / CHANGED  
 1554 SHT / CHANGED  
 1555

ORIGINATED BY	S.J.C.
DATE	16.4.52
SIGNED FOR COMMITTEE	P.1.8