


RELAY CODES & COMPONENTS LIST, GBW 12511.
FAULT SERVICE TURRET CIRCUITS

RELAY	BCC CODE	DIA FIG	NOTES	COMPT DESIGNATION	BPO CODE	NOTES
PR	2012	1B		R1	Nº 6	FIGS. 2A, 2B (MTD. ON C3)
PR	76984	1C		R2	Nº 9	" 3
I	6137	2A		R3	35B	" 3 (MTD. ON LP.1)
I	6485	2B		R4	35B	" 2B (MTD. ON LP.1)
LA	60967	2B		R5	Nº 9	" 1B
				C1	103C	" 1A
				C2	102A	" 1A
				C3	102A	" 2A, 2B
				C4	102A	" 2B
				KA	236	" 3
				KD+KAB	236	" 2B
				KD	207	" 2A
				KFS	289	" 4
				MRI	2/2AZ	" 1A
				IC	3/16	" 1A
				JK	84A	" 1A
				ADA	-	" 2A, 2B
				ADA/MTG	18/2	" 2A, 2B
				ADA/SC	1/SST/78	" 2A, 2B
				LP/MTG	10A	" 2B, 3
				TS	121	" 2A, 2B, 3

NOTES - A SPECIAL FACTORS OF SAFETY. B SPECIAL ADJUSTMENTS. C CCT. POINTS OR MODIFICATIONS.

LAYOUT



KEY TURRET

TURRET BASE. PLAN VIEW.



TURRET TOP. PLAN VIEW.

NOTES.

1. ANSWERING KEYS TO GBW 16700 FIG. IF MAY BE USED IN PLACE OF GBW 12511 FIG. 3

N.Z.P.O. R.C.
(13131) 23-12-69

ISSUE 1. 19. 11. 58 APP	ALTERNATIVE MTG FOR R2 WAS NOT SHOWN. RETRACED	ISS. 2 23. 11. 59. WAS CRDS LA WAS 70335 I (2B) WAS NOT SHOWN.	ISS. 3. 16. 2. 60 R5 ADDED R4 WAS TYPE NO 12. MRI REVISED CODE LAYOUT REVISED JK 4025 ADDED	ISS. 4. 19. 6. 62 NOTE C1 ADDED	ISS. 5. 12. 2. 64 R3, R4 WERE #6 JK WAS 4025. C4, IC, TS, ADA CODES ADDED REDRAWN.	ISS. 6. 1. 4. 69. NOTE C1 DELETED NOTE 1 ADDED (2080)	ISS. 7. 2. 872
-------------------------	--	--	---	---------------------------------	--	---	----------------

ORIGINATED BY	S.T.C.
DATE	19. 11. 58.
SIGNED FOR COMMITTEE	D.H.O.