

RELAY CODES & COMPONENTS LIST, GBW 14200
 MANUAL BOARD CIRCUITS
 50/1200 LINE P.A.B.X.

5 Centimetres

10

15

20

25

30

RELAY	BCC CODE	DIA FIG	NOTES	COMPT DESIGNATION	BPO CODE	NOTES
DA	60635	1A		IC	P.O.3/16 COIL INDUCT.	FIG. 1A
DN	60622	1A		MRI	2/2 AZ	FIG. 1A
DS	60639 P	1A		C1	102	FIG. 1A
PR	61545 P	1A		C2	"	"
WP	HS706	1B	B1	C3	"	"
FA	5220	4		C4	"	"
CT	6818	6		C5	"	"
				R1		FIG. 1A IN WIRING
				R2	6	" " "
				R3	9	FIG. 7
				R4	9	FIG. 6
				R5	9	"
				R6	12	FIG. 1A
				R7	6	FIG. 4
				R8	6	FIG. 2
				R9	6	" IN WIRING
				R10	6	FIG. 1A " "
				R11A	12	FIG. 1B
				R11B	12	"
				R12	12	FIG. 1A
				R13	6	FIG. 1B IN WIRING
				R14	6	FIG. 1A " "

NOTES - A SPECIAL FACTORS OF SAFETY, B SPECIAL ADJUSTMENTS, C CCT. POINTS OR MODIFICATIONS.

LAYOUT
FRONT VIEW



MOUNTING B.P.O. F.151/18AH

N.Z. P.O.
(94164) 11-6-65

ISSUE 1. 18.3.63 APP
 WAS C.R.D.S.
 PR RELAY WAS
 BCC 50164 P
 GH RELAY
 DELETED
 RESISTORS
 REARRANGED

ISS. 2 1964

ORIGINATED BY	S.T.C.
DATE	18/3/63
SIGNED FOR COMMITTEE	R.E.D.