


RELAY CODES & COMPONENTS LIST, **GBW 14880**  
MANUAL TEST CABINET FOR BOTHWAY 2-V.F. TOLL LINE  
CIRCUITS

DIAG FIG	BCC CODE	RELAY	NOTES	COMPT DESIGNATION	BPO CODE	NOTES
	4073	DT		R1.R2	No 9	
	1298	FC	B	R4.R6		
	2012	RA	RETARD	R16	No 12.	
	50107	DTA		R3R5		
	2231	RD		R8R9		
	HSD513	PD	B	R10R11	No 26 GC.	R12 MTD ON C1, R13 MTD ON C2
				R12R13		R14 MTD ON C4
				R14	No 6	R15 MTD ON C3
				R15		
				C1.C2C4	102	
				C5	7740	
				C3	7710	
				MRI	2/2AZ.	
				IC	3/16	
				ADA	N.Z.P.O. STD.	
				JKA	No 19 MK.2	
				KS	253	
				KR+KD	174	
				KA+KC	212	

NOTES:- A.SPECIAL FACTORS OF SAFETY.B.SPECIAL ADJUSTMENTS.C.CCT. POINTS OR MODIFICATIONS

LAYOUT.

R1/R2/R4	R3/R8/R9/ R10/R11
R6/R7/ R16	DT
IC	DTA
	FC
C1 (R12)	RA
C2 (R13)	RD
C4 (R14)	R5 MRI
C5 C3 (R15)	PD



LAYOUT OF EQUIPT. ON LID

ISSUES 27 9-57 DTA WAS 7606 ISSUE 4 8-13-60 RD & PD, R16 R17 WERE NOT SHOWN. C3 & C5 WERE 103 & 101 RESP. BY ISSUE 5 R17 WAS SHOWN 2-1-65 BR ISSUE 6	ORIGINATED BY	AEI
	DATE	8-11-56
	SIGNED FOR COMMITTEE	Ash. J.