


RELAY CODES & COMPONENTS LIST, **GBW 15051**
 DEPENDENT EXCHANGE OR LINE CIRCUIT FOR
 BOTHWAY JUNCTIONS TO PARENT EXCHANGES
 N.Z.S.S. A.C. NO. 3.

RELAY	B.C.C. CODE	DIAG. FIG.	NOTES	COMPT. DESIGNATION	BPO CODE	NOTES
A	HSD702		TEST AND R.A. FIGURES	R1-R6	No 9	
AA	HSD701			R12-R14 R19,R20		
AK	5953			R15,R16	No 12	
B	5954			R7-R11	No 15	
BB	5891			R21-R24		
BR	5955			R17	No 6	MOUNTED ON C5
CB	6383			R18		MOUNTED ON C1
CD	5956			C1&C5	7510	
CF	5893			C4	7725	
CH	5957			C2A,C2B	103C MK 2	
CR	5923P			C3	102	
D	1469			RX2,RX5	NON-LINEAR No 2	MOUNTED IN WIRING OF PART 1.
DB	5958			RX1,3&4	NON-LINEAR No 2	" " " " PART 2.
DC	5959			TI	415A A.E.I. CODE	ON ALL EARLY EQUIPT. THIS WAS 113A
DD	5960			VUI	1001 A.E.I. CODE	
DX	5961P			MRI-3	1/12AZ	

NOTES:- A. SPECIAL FACTORS OF SAFETY. B. SPECIAL ADJUSTMENTS. C. C.T. POINTS OR MODIFICATIONS.

LAYOUT.

FIG. 1A PART 1.



N.Z.P.O.
 (69189) 20.9.63 R-6.
 ISSUE 1 APP
 16-7-63
 NO CHANGE
 ISSUE ONLY
 ADVANCED
 (72207) A.60
 ISSUE 2
 6.1.64

ORIGINATED BY	A.E.I.
DATE	16/7/63
SIGNED FOR COMMITTEE	Ash 8/7



RELAY CODES & COMPONENTS LIST, GBW 15051
 DEPENDENT EXCHANGE O/G LINE CIRCUIT FOR
 BOTHWAY JUNCTIONS TO PARENT EXCHANGES
 N.Z.S.S. A.C. No 3.

RELAY	B.C.C. CODE	DIAG. FIG.	NOTES	COMPT. DESIGNATION	BPO CODE	NOTES
LA	7083					
LB	5962					
MH	10421					
RG	60546					
RL	5963					
SA	5964P					
SB	5925					
SP	HSD524		TEST AND R.A. FIGURES			
SR	5942					
SS	5965					
TX	HSD512		TEST AND R.A. FIGURES			
WA	5966					
WB	5967					
WS	5968					

NOTES:- A. SPECIAL FACTORS OF SAFETY. B. SPECIAL ADJUSTMENTS. C. CCT. POINTS OR MODIFICATIONS.

LAYOUT.

FIG. 1B. PART 2



† GUARD FITTED

NOTES.
2.1 ON EARLY EQUIPMENT RELAY SP WAS HSD 514.

N.Z.P.O.
(2189) 20.9.63 S.L.
ISSUE 1
16-7-63
NOTE 2: ADDED (72207)
ISSUE 2
6-1-64

ORIGINATED BY: A.E.I.
DATE: 16/7/63
SIGNED FOR COMMITTEE: Ash [Signature]