

# RELAY CODES & COMPONENTS LIST, GBW 15060

PARENT EXCHANGE I/C LINE CIRCUIT N.Z.S.S.A.C. No 3 FROM

DEPENDENT EXCHANGE

DIAG FIG	BCC CODE	RELAY	NOTES	COMPT DESIG-NATION	BPO CODE	NOTES
	5897 P	A	B1 TEST AND READJUST FIGS.	R2-R5a&b	No 15	
	5943 P	AK		R6, R17	No 12	
	HSD511	AX	B2 TEST AND READJUST FIGS.	R7-R10	No 9	
	5944	B		R16		
	5945	BB		R11		
	5946	BR		R12, R13	No 15 GD	
	50113	CD		R18		
	5936	D		R14	No 6	
	5901	DA		R15	No 6	
	4088	DB		C1	102C	
	5902 P	DR		C2, C3, C7	101	
	1105	DY		CA	119	
	5948	DZ		C5, C6	100	
	10730	MB		MR1	1/2 AZ	
	4320	MH		MR2	2P/6AZ	
	72399	RL		MR3-5	1/12 AZ	
				URI	RES. ASSEM 1077	AEI CODE
				T1	194 A	
				T2	196 A	
				T3	195 A	
				T4	415 A	
				RX1-5	NON LINEAR No 2	MTD. IN WIRING
				V1-V2	C V13B OR EQUIV.	
				PLUG	3201 MK. 2.	
				R19-21	RADIO TYPE	MTD IN WIRING
				R1	NO 15	NOT WIRED
				R22-23	RADIO TYPE	MTD IN WIRING

NOTES:- A. SPECIAL FACTORS OF SAFETY. B. SPECIAL ADJUSTMENTS. C. CCT. POINTS OR MODIFICATIONS.

FRONT VIEW.

LAYOUT.

RS	V2	V1
RLA		T1
WB	R13 R12	T2 R18
∅ A	T3	
AX	T4	
B	D	
BR	DR	+
CD	TY	
DA	BB	
TX	DZ	
AK	MB	
DB	RL	
WC	WA	+
MH	X	
SC	DY	

∅ FITTED WITH COVER.  
+ FITTED WITH GUARD.

REAR VIEW

R3	R1	R2
R5A	R5B	R6
R9	R7	R8
	R10	R16
	R17	
	MR1	
	MR2	
PLUG 3201 MK. 2		
C6		
C7		
	C2	R15
	C3	R14
	C4	
	C5	
	C1	
URI		MR4
MR3		MR5

C1. RESISTORS R11, 12, 13 & 18 TO BE COVERED WITH SLEEVING OF AN APPROVED TYPE.

NZPO (63553) 16762 PAK

ISSUE 1 17-5-62 TITLE AMENDED LAYOUT REVISED C1 WAS 102. R1, R12, R13 & R18 WAS No 14 W. 5% (7221)	ISSUE 2 31-12-63 RX5 WAS NOT SHOWN. TITLE AMENDED. (91570)	ISSUE 3 20-10-64 NOTE C1 WAS NOT SHOWN (47244)	ISSUE 4 11-11-64 R5 a&b WERE NOT SHOWN (81753)	ISSUE 5 4-9-67 OR EQUIV. ADDED TO V1-V2 CODE (21621)	ISSUE 6 18-12-65 R19-23 ADD. R1 DELETED FROM WIRING (193362)	ISSUE 7 15-5-6A 2-5-78
ORIGINATED BY AEI						
DATE 17-5-62						
SIGNED FOR COMMITTEE <i>Asst P...</i>						

