

RELAY CODES & COMPONENTS LIST, **GBW 15081**
 DEPENDENT EXCH. 1C IVF LINE CCT FROM PARENT EXCH.

RELAY	B.C.C. CODE	DIAG. FIG.	NOTES	COMPT. DESIGNATION	BPO CODE	NOTES
A	5897P		TEST AND R.A. FIGURES. B.	R2	15	
AK	5934P			R3,R4	15	
AX	HSD511		TEST AND R.A. FIGURES. B.	R5A,5B	15	
B	5929			R6-7-8	9	
BR	5930			R10-R11	6	MTD. ON C3 & C2
CD	5931			R14-R15	12	
CR	71199			R9	15G	MOUNTED ON T1 CLOSE TO V1.
D	5936			R12	15E	MOUNTED ON T2
DA	5901			R13-R16	15F	
DR	5902P			MR1	1/2AZ	
IG	5933			MR2	2P/6AZ	
RG	7739			MR3-4	1/12AZ	
RP	5932			C1	102	
RR	5937			C23-7	101	R10 R11
RS	4034			C4	119	
TY	HSD506		TEST AND R.A. FIGURES. B.	C5-6	100	
				V1-V2	CV138	
				T1	194A (AEI)	R9
				T2	196A "	R12 R13 R16
				T3	195A "	
				T4	415A "	
				RX1-4	NON-LIN No2	MTD. IN WIRING
				URI	RES. ASS1077	AEI CODE
				UPT. PLUG	3201 MK2	
				R1	15	NOT WIRED
				R17-19	RADIO TYPE	MTD IN WIRING

NOTES:- A. SPECIAL FACTORS OF SAFETY. B. SPECIAL ADJUSTMENTS. C. CCT. POINTS OR MODIFICATIONS.

LAYOUT

RESISTORS TO BE COVERED WITH SLEEVING OF APPROVED TYPE. RX1-RX4, TO BE MTD. IN WIRING. ϕ COVER FITTED. \times GUARD FITTED.

URI	V2 VI
X	T1 R9
A	T2 R12-13-16
B	T3
BR	T4
CD	D
DA	DR
TX	AX
RS	AK \times
RP	RR
RG	IG
CR	TY

FRONT VIEW

CANCELLED
 REVERT TO GBW 15080

ISSUE 1 6-12-62 R.C.C.L. CANCELLED (69187)	ISSUE 2 22-7-63 R17-19 ADDED. R1. DELETED FROM WIRING (19338)	RWK 155 2A 2-5-78	ORIGINATED BY AEI
N.Z.P.O. 19-2-63 (66420) B.L.			DATE 6.12.62
			SIGNED FOR COMMITTEE A. J. Ash

