

RELAY CODES & COMPONENTS LIST, **GBW 15091**
 DEPENDENT EXCH. O/G N.Z.S.S. A.C. NO 3 LINE CCT.
 FOR UNIDIRECTIONAL JUNCTIONS TO PARENT EXCHANGE.

RELAY	B.C.C. CODE	DIAG. FIG.	NOTES	COMPT. DESIGNATION	BPO CODE	NOTES
A	HSD 702		TEST AND R.A. FIGURES	R1-R6	No 9	
AA	HSD 701		TEST AND R.A. FIGURES	R12-R13		
				R14		
AK	5953			R19,R20	No 15	
B	5954			R7-R11		
				R25,R27		
BB	5891			R28-R30	No 12	
BR	5955			R24		
				R15,R16		
CB	6383			R21	15 GD	TO BE COVERED WITH SLEEVING OF APPROVED TYRE.
CD	5956			R22	15 ED	
				R23,26	15 FE	
CF	5893			R17	No 6	MOUNTED ON C5
CH	5957		TEST AND R.A. FIGURES	R18		
CR	5923P			C1,C5	7510	MOUNTED ON C1
D	1469			C9	7725	
				C4		
DB	5001			C6,C8	100	
DC	5959			C2A,C2B	103C MK 2	
DD	5960			C7	119	
DX	5961P			C3	102	
				RX1-5	NON-LINEAR No 2	MOUNTED IN WIRING.
				MRI-3	1/12AZ	
				V1,V2	CV138 OR EQUIV.	TO BE CALLED FOR SEPARATELY.
				T1	415A	ON ALL EARLY EQUIPT. THIS WAS 113A
				T2	196A	
				T3	195A	
				T4	194A	

NOTES:- A.SPECIAL FACTORS OF SAFETY.B.SPECIAL ADJUSTMENTS C.CCT. POINTS OR MODIFICATIONS


LAYOUT.
PART 2

FRONT VIEW

VUI	V2 VI
AK	T4
B	T3
BB	T2
TX	DB
X	DC
RL	SR
DX	CR
BR	CD
RG	CF
C9 C5	C1 C4

+ GUARD FITTED

REAR VIEW



RX1, RX3 & RX4 MTD. IN WIRING.

N.Z.P.O. (74746) 7.8.63 A.6.

ISSUE 1 4-7-63 NO CHANGE ISSUE ONLY ADVANCED (72200)	ISSUE 2 16-1-64 NO CHANGE ISSUE ONLY ADVANCED (91647)	ISSUE 3 11-11-64 FOR EQUIV. ADDED TO VI-V2 CODE (21626)	ISSUE 4 15-12-69
---	--	---	---------------------

ORIGINATED BY	A.E.I.
DATE	4/7/63
SIGNED FOR COMMITTEE	Ash

RELAY CODES & COMPONENTS LIST, GBW 15091

DEPENDENT EXCH. O/G N.Z.S.S. A.C. No 3 LINE C&T.

FOR UNIDIRECTIONAL JUNCTIONS TO PARENT EXCHANGE.

RELAY	B.C.C. CODE	DIAG. FIG.	NOTES	COMPT. DESIGNATION	BPO CODE	NOTES
LA	7083			PLUG	No 6	SHORTING LINK 'N'
LB	5962			UPT. PLUG	3201 MK.2.	
MH	10421					
RG	10808					
RL	5963					
SP	HSD 524		TEST AND R.A. FIGURES			
SR	5942					
SS	5965					
TX	HSD 512		TEST AND R.A. FIGURES.			
WA	5966					
WB	5967					
WS	5968					
X	HSD 513		TEST AND R.A. FIGURES.			

NOTES: - A. SPECIAL FACTORS OF SAFETY. B. SPECIAL ADJUSTMENTS. C. CCT. POINTS OR MODIFICATIONS.


LAYOUT.

PART I.

FRONT VIEW

RI	R2	R3	R4	R19	R20
A			TI		
AA			CR		
LA			CH		
LB			MH		
WA			D		
WS			DD		
WB			SP		
SS			MR2	MR3	

REAR VIEW



RX2 & RX5 MTD. IN WIRING.

+ GUARD FITTED

NOTES: 2" ON EARLY EQUIPMENT RELAY SP WAS HSD514

N.Z.P.O. (74746) 7.8.63. 8.6.

ISSUE 1 4-7-63 NOTE 2.1 ADDED (72209)	ISSUE 2. 6.11.64. DEPOINT PLUG WAS NOT SHOWN. (91647)	ISSUE 3. 11.11.64. NO CHANGE (21626)	ISSUE 4 18-12-69
---	---	---	---------------------

ORIGINATED BY	A.E.I.
DATE	4/7/63
SIGNED FOR COMMITTEE	<i>[Signature]</i>