

RELAY CODES & COMPONENTS L. ST, GBW 15150

1/C JUNC. OR SEL. LEVELS TO SPEC. SERVICE LINES


W/-OR W/O MANUAL HOLD & NEGATIVE IMPEDANCE
REPEATER SWITCHING

RELAY	BCC CODE	DIA. FIG.	NOTES	COMPT. DESIGNATION	BPO CODE	NOTES
A	1426 A		B	R1	9	200 Ω
				R2	9	300 Ω
B	60706			R3	9	400 Ω
DA	50203			D1	CV8308 OR EQUIV.	WIRED ON DD RELAY
				D2	CV8308 OR EQUIV.	WIRED BETWEEN F&RR RELAY
DD	61069			C1	102 C	
				C2	102 C	
F	1121					
RR	6030			TJ	21H	
				RX1	NON-LIN'R №2.	WIRED ACROSS 'B' RELAY
RELAY DRIVER	NZ43290			D3	CV8308 OR EQUIV.	WIRED BETWEEN A&B RELAYS
				D'4	CV8308 OR EQUIV.	WIRED BETWEEN A&F RELAYS
				D5	IN40070REQU.	
				R4	9	1.2 K.Ω

NOTES - A SPECIAL FACTORS OF SAFETY. B SPECIAL ADJUSTMENTS. C CCT. POINTS OR MODIFICATIONS.

LAYOUT

RBI	RI/R2/R3
A *	DA
B	DD
F	RR
TJ	



* FITTED WITH SHIELD BPO 1/SSH/1

+ NOTE: NZPO 43290 MAY BE REPLACED BY LOCALLY MOUNTED COMPONENTS AT SOME EXCHANGES.

NZPO

(2292) 5-2-73 D.L.M.

ISSUE 1	AMD. TO NZM VZ (038447)	ISS 1A 28.9.83
---------	-------------------------	----------------

ORIGINATED BY	S.T.C.
DATE	8-5-69
SIGNED FOR COMMITTEE	A.H.W.