

RELAY CODES & COMPONENTS LIST GBW 15191
ROUTINER FOR GROUP SELECTOR WITHOUT
BUSY FLASH. TEST UNIT 2000 TYPE

RELAY	B.C.C. CODE	DIAG FIG	NOTES	COMP. DESIGNATION	BPO CODE	NOTES
A	6119			C1	P.0.101	
AE	20517		SPRINGS 25&26 NOT WIRED	C3		
AO	1005			C2	P.0.102	
AR	6535		SPRING 3 NOT WIRED. TEST AND R.A. FIGURES	R1		
B	4365			R5	No 6	
BA	5722		SPRINGS 23 & 24 NOT WIRED	R6		
BB	5722		SPRINGS 23 & 24 NOT WIRED	MR1	4/6AZ	
BI	71557			MR7		
BT	40695 Pd			MR2	1/12AZ	
CF	4073			MR8		
CQ	6197		SPRINGS 1, 8, 9, 23, 24 & 25 NOT WIRED	MR9		
DC	5868			MR3		
DD	5875			MR4	2N/6AZ	
DE	5723			MR5		
DR	20519		SPRING 5 NOT WIRED.	MR6		
DS	4295			T	2/87AN	
				S		
				C4		AH HUNT TYPE W99
				C5		
				RX1	2	

NOTES - A. SPECIAL FACTORS OF SAFETY B. SPECIAL ADJUSTMENTS C. OCT. POINTS OR MODIFICATIONS

LAYOUT.




FIG 1

* RELAY SHIELD PO. N° 65H/1.

N.Z.P.O (69004) 5-9-63 B.6.

ISSUE 1 12 JUNE 1963 C4 & C5 WERE NOT SHOWN (69407)	ISSUE 2 23-9-63 SHIELD WAS NOT SHOWN ON RELAY B1 (58183)	ISSUE 3 30.11.65 BT RELAY CODE WAS G010, RX1 D1 & D2 ADDED (122319)	ISS. 3A 2-10-74 KG RC ADDED (193570)	ISS. 3B 8-12-78 (MAY) NO CHANGE. SHT. 4. AMD (38443) FB ISS. 3C 5-10-83.	ORIGINATED BY AEI
DATE 12 TH JUNE '63					
SIGNED FOR COMMITTEE Ash					

RELAY CODES & COMPONENTS LIST, **GBW 15191**
ROUTINER FOR GROUP SELECTOR WITHOUT BUSY FLASH. TEST UNIT. 2000 TYPE

RELAY	B.C.C. CODE	DIAG. FIG	NOTES	COMPT. DESIGNATION	BPO CODE	NOTES
DU	1423			R2-R4	N°9	
DV	1618			R10-R12		
FD	5869			R14, R15	N°9A	
FG	5870			R27, R28		
FH	5871			R8, R13	N°12	
GQ	6197		SPRINGS 7, 8, 9, 23, 24, 25, NOT WIRED	R7, R9		
H	1816		SPRINGS 1, 2, 3, 7, 23, 24, 25, 26, 27, 28 & 29 NOT WIRED	R16-R21	N°12A	
HA	60005			R24-R26		
HB	60005			R22		
HR	HSD506		SPRING 3 NOT WIRED	R23		
IP	2017					
IQ	10313P					
IR	10313P					
KA	HS711					
KB	HS711					
LA	10322		SPRINGS 1, 2 NOT WIRED			

NOTES:- A. SPECIAL FACTORS OF SAFETY. B. SPECIAL ADJUSTMENTS. C. CCT. POINTS OR MODIFICATIONS.

LAYOUT.




FIG 3

N.Z.P.O. (G9004) 5.9.63. 3.6.

I.S. SUE 1 12 TH JUNE 1963 NO CHANGE ADVANCE IN ISSUE ONLY (69407)	155.2 23.9.63. ISSUE ADVANCED. NO CHANGE. (50183)	ISSUE 3 30.11.65. NO CHANGE ADVANCED IN 155. (122319)	155.3A. 2.10.74 KG R29, R30 ADDED (193570)	155.3B. 8.12.78 WMM NO CHANGE. SHT 4 AND (39443) FB 155.3C. 5.10.83	ORIGINATED BY	AEI
					DATE	12 TH JUNE '63
					SIGNED FOR COMMITTEE	ASH

ROUTINER FOR GROUP SELECTOR WITHOUT BUSY FLASH. TEST UNIT 2000 TYPE

RELAY	BCC CODE	DIAG. FIG.	NOTES	COMPT. DESIGNATION	BPO CODE	NOTES
LB	10322		SPRINGS 1 & 2 NOT WIRED	KDSFI	P.O.72	
LC	1425			KPBF1	P.O.68	
LD	1425			KNFI / KPFI	P.O.212	
LI	20507			KBFI	P.O.68	
LT	5815			KIC / K2C	P.O.212	
NL	10068		SPRINGS 3&4 NOT WIRED, TEST AND RA FIGURES	KBT	P.O.68.	
PA	HS521		TEST RA FIGURES	LPI-34	P.O.Nº2/6V	
PB	2318		SPRINGS 23-29 NOT WIRED.	R29/30	Nº9	
PE	5911			D1		IN 4003
PF	10137			D2		IN 4003
PG	20521		SPRINGS 3,4,21&22 NOT WIRED	D3		IN 4003
PH	7288			D4		IN 4003
PL	10068		SPRINGS 3&4 NOT WIRED, TEST AND RA FIGURES	D5		IN 4003
PO	1005					
PP	HSD506		SPRING 23 NOT WIRED, TEST AND RA FIGURES			
PT	HS522		TEST AND RA FIGURES			

NOTES:-A SPECIAL FACTORS OF SAFETY. B SPECIAL ADJUSTMENTS. C CCT. POINTS OR MODIFICATIONS

LAYOUT




FIG. 2

NZPO (69004), 5-9-63 BC.

ISS.1. 12-6-63 APP. NO CHANGE IN ADVANCE IN ISSUE ONLY. (69407)	ISS.2. 23-9-63 BC. NO CHANGE IN ADVANCE IN ISSUE (58183)	ISS.3. 30-11-65 NC. NO CHANGE IN ADVANCE IN ISSUE. (122319)	ISS 3A 2-10-74. KG D1-D5 ADDED (193570)	ISS 3B 8-12-78. WHH NO CHANGE. SHT 4 AND (38443) FB	ISS. 3C 5-10-83
---	--	---	---	---	-----------------

ORIGINATED BY	AEI
DATE	12 JUN. 63.
SIGNED FOR COMMITTEE	

RELAY CODES & COMPONENTS LIST, **GBW 15191**
ROUTINER FOR GROUP SELECTOR WITHOUT
BUSY FLASH TEST UNIT 2000 TYPE

RELAY	B.C.C. CODE	DIAG. FIG.	NOTES	COMPT. DESIGNATION	BPO CODE	NOTES
PTA	HSD740		SPRING 23 NOT WIRED. TEST & R.A. FIGURES			
PW	5423					
PX	20522		SPRING 7 NOT WIRED			
PY	20523					
PZ	5872					
RT	72980					
SG	10147		SPRINGS 21,22 NOT WIRED.			
SR	5873					
SS	10146					
SZ	20525					
TA	HS521					
TD	4031		SPRINGS 3,4 NOT WIRED			
TQ	7832					
TR	6035					
TS	10333		IN FIG 1A ONLY SPRINGS 25,26 NOT WIRED.			
TU	N.Z. 50680 AD					

NOTES:- A.SPECIAL FACTORS OF SAFETY.B.SPECIAL ADJUSTMENTS.C.CCT. POINTS OR MODIFICATIONS.

LAYOUT.

N.Z.P.O.(69004) 5-9-63. A.G.

ISSUE 1 12 th JUNE 1963 NO CHANGE ADVANCE IN ISSUE ONLY (69407)	ISSUE 2 28.9.63 ISSUE ADVANCED NO CHANGE. (58183)	ISSUE 3 30.11.65. NO CHANGE ADVANCED IN ISS. (122319)	ISS. 3A 2-10-74. KG NO CHANGE SHTS 12.3&5 AMENDED (193570)	ISS 3B 8-12-78 N.Z. 50680 AD AM (38443) FB ISS. 3C 5-10-83	ORIGINATED BY AEI
DATE 12 th JUNE '63'					
SIGNED FOR COMMITTEE <i>ASH</i>					

RELAY CODES & COMPONENTS LIST, **GBW 15191**
ROUTINER FOR GROUP SELECTOR WITHOUT
BUSY FLASH. TEST UNIT. 2000 TYPE

RELAY	B.C.C. CODE	DIAG. FIG.	NOTES	COMPT. DESIGNATION	BPO CODE	NOTES
WF	5725		SPRINGS 6,7,8 NOT WIRED			
WG	5726					
WH	6050					
Z	5874					
RC	1524					

NOTES:- A.SPECIAL FACTORS OF SAFETY.B.SPECIAL ADJUSTMENTS.C.CCT. POINTS OR MODIFICATIONS.

LAYOUT.

NZPO (69004) 5-9-63. R.L.

ISSUE 1 APP 12 th JUNE 1963 NO CHANGE / ADVANCE IN ISSUE ONLY (69407)	ISSUE 2 23-9-63.	ISSUE ADVANCED NO CHANGE. (58183)	ISSUE 3 30.11.65. NO CHANGE ADVANCED IN ISS. (122319)	ISS 3A 2-10-74 KG RC ADDED (193570)	ISS 3B 8-12-78 WWH NO CHANGE. SGT. 4. AMP (38443) FB ISS. 3C. 5-10-83	ORIGINATED BY AEI	DATE 12 th JUNE '63	SIGNED FOR COMMITTEE AHG
---	---------------------	--	---	---	--	----------------------	-----------------------------------	-----------------------------