


RELAY CODES & COMPONENTS LIST, GBW 15201  
 MANUAL BOARD CIRCUIT  
 50/1200 LINE P.A.B.X.

RELAY	BCC CODE	DIA FIG	NOTES	COMPT DESIGNATION	BPO CODE	NOTES
DA	60635	1A		IC	PO 3/16 COIL INDUCT.	FIG. 1A
DN	60622	1A		MRI	2/2 AZ	FIG. 1A
DS	60639 P	1A		C1	102	FIG. 1A
PR	61545 P	1A		C2	"	" 1A
WP	HS 706	1B		C3	"	" 1A
FA	5220	5		C4	"	" 1A
				C5	"	" 1A
CT	6818	7		R3	9	FIG. 4
				R4	9	FIG. 7
SA	HSD 101	1A		R5	9	" 7
SB	HSD 511	1A		R18	9	" 1A
				R19	9	" 1A
SC	HSD 101	1A		R20	9	" 1A
HA	6596	1A		R15	12	" 1A
HC	6596	1A		R16A	12	FIG. 1B
				R16B	12	" 1B
SW	2005	1A		R13	9	FIG. 1A
GH	70879	4		R2	6	IN WIRING ON C5
				R1	6	IN WIRING ON C3
				RXI	Nº2 NON LINEAR	IN WIRING ON DA


NOTES - A SPECIAL FACTORS OF SAFETY, B SPECIAL ADJUSTMENTS, C CCT. POINTS OR MODIFICATIONS

LAYOUT  
FRONT VIEW



UPPER MTG.

MOUNTING B.P.O. F149/12 BH



LOWER MTG.

MOUNTING B.P.O. F151/18AH

SEE SHT. 2

C.F.E.

N.Z.P.O.  
(8484) 17.5.71

ISSUE 1  
UPPER PLATE  
SHEWED IS MTR  
POANS ONLY  
SCB WAS SCA  
155.2

ORIGINATED BY	S.T.C.
DATE	RS 11-13
SIGNED FOR COMMITTEE	69. 11. 13

