

RELAY CODES & COMPONENTS LIST, GBW 15211

CORD CIRCUIT

50/1200 LINE P.A.B.X.

RELAY	BCC CODE	DIA FIG	NOTES	COMPT DESIGNATION	BPO CODE	NOTES
LA	60654		BI	R1	Nº9	
LC	NOTE. A		BI	R2	"	
AS	60906		BI	R3	"	
CS	60906		BI	C1	102 C	
DR	71552			C2	"	
SK	60795			MRI	-	MFRS. CODE - DA000
SR	60908			MR2	1/12 AZ	
D	60075		BI	MR3	1/12 AZ	
				MR4		CV 8308

NOTES - A SPECIAL FACTORS OF SAFETY. B SPECIAL ADJUSTMENTS. C CCT. POINTS OR MODIFICATIONS.
BI - TEST & RE-ADJUST FIGURES APPLY

LAYOUT

1AS	1SK
1CS	1SR
1D	1LA
1DR	1LC
2AS	2SK
2CS	2SR
2D	2LA
2DR	2LC
3AS	3SK
3CS	3SR
3D	3LA
3DR	3LC

FRONT VIEW

1R1	1R2	1R3	-D
2R1	2R2	2R3	-E
3R1	3R2	3R3	-K

E2

1C1
1C2

D4

2C1		
2C2		
3C1		
3C2		
1MR2	1MR3	-C
2MR2	2MR3	-B
3MR2	3MR3	-A

PLUGS - 2 X 32 PT.
TEST JACK - 2 PT.

NZPO NOTE. A
LC RELAY CODE IS
NZPO 54228 FD (13)

NOTE: 1MRI, 2MRI, 3MRI,
ARE WIRED ACROSS
RELAY SPRINGS AND
1MR4, 2MR4, 3MR4 ARE
WIRED ON RELAYS 1LC-3LC

N.Z.P.O.
(122568) 14-2-74

ISSUE 1.
LC WAS
BCC 60654.
MR4 ADDED
ISS. 2. GFE

ORIGINATED BY	S.T.C.
DATE	25-11-65
SIGNED FOR COMMITTEE	<i>[Signature]</i>