


RELAY CODES & COMPONENTS LIST, **GBW 15670**  
50v POSITIVE SUPPLY (TRANSISTOR) FAIL ALARM  
RELAY SET I.V.F. SYSTEM

RELAY	BCC CODE	DIAG. FIG.	NOTES	COMPT. DESIGNATION	BPO CODE	NOTES
AF	11351			MRI-3	BTH GJ 3M	MTD. ON SCA
BF	11351			MR4-6	GG81-H	MTD. IN WIRING
CF	11351			MR7-12	VR12F	MTD. ON SCA
AL	6005			SCA	STRIP CONN. 145	C.
				KLC		
				RI		
				LPI	JACK 211	JACK 95 SUPERSEDED
				TJI-8		
				PLUG	1603 MK.2	
				TJ9-14	JACK 186	


NOTES: - A. SPECIAL FACTORS OF SAFETY. B. SPECIAL ADJUSTMENTS. C. CCT. POINTS OR MODIFICATIONS.

LAYOUT.




NOTES.  
 C. RECTS. MR7, 9 & 11. MOUNTED ON HIGHER PLANE THAN RECTS. MR8, 10 & 12.

FRONT VIEW



REAR VIEW



ISSUE 1. 17-10-61 MR7-12, SCA TJ9-14 WERE NOT SHOWN RELAYS AF, BF & CF CODE WAS 4012. RE TRACED ISSUE 2 14-7-64	NZPO. (47208) 29-1-65. R.L.	ORIGINATED BY A.E.I.
	DATE. 17.10.61	SIGNED FOR COMMITTEE Ash

Centimetres