

RELAY CODES & COMPONENTS LIST


GBW 16600

ROUTINER ACCESS SELECTOR FOR 200 LINE F/S WITH TOLL ACCESS,
11-20 P.B.X., UNISELR. ACC. SELR. MOUNTED ON FINAL SELECTOR RACK, 2000 TYPE.


RELAY	BCC CODE	DIAG. FIG.	NOTES	COMPT. DESIGNATION	BPO CODE	NOTES
OA	7322			A	ASSY 4D/54462	(G.E.C. CODE) U/S MECHANISM.
					2/12/1.	BANK CONTACT.
OB	7322			CI	№ 7732	CAPACITOR
OD	6001				№ 121	STRIP CONNEXION MTD ADJACENT TO ACCESS SWITCH.
					№ 170/6A	STRIP CONNEXION (RTR. ACC.)

NOTES A. SPECIAL FACTORS OF SAFETY. B. SPECIAL ADJUSTMENTS. C. CCT POINTS OF MODIFICATIONS.


LAYOUT



STRIP CONNS. P.O.#170/6A MOUNTED ON RACK TOP ANGLE IN POSN. 1.



RTR. ACC. SELR MTD. ON REAR OF SHELVES 'A', 'C' & 'D' OF 11-20 P.B.X. F/S RACK.



TEST LINE ACC. RELAYS MTD. ON RIGHT HAND RACK UPRIGHT.

5 Centimetres
10
15
20
25
30

N.Z.P.O. KG
(122523) 2974

ISSUE 1.
16.6.72.

ORIGINATED BY	G.E.C.
DATE	15-6-72.
SIGNED FOR COMMITTEE	R.I. Jones