

RELAY CODES & COMPONENTS LIST, GBW 16671 MODA
 UAX NZ13 OUTGOING JUNCTION TERMINAL UAX
 TO PARENT EXCHANGE

RELAY	BCC CODE	DIAG. FIG	NOTES	COMPT. DESIG NATION	BPO CODE	NOTES
A	HSD702			R1	N°9	
B	16056			(R2)		1/4 WATT. 10%
CD	74599			(R3)	N°6	
CA	12578			R4	N°9	
BB	5001			R5	N°9	
NU	15655			R6	N°9	
WS	1941			R7	N°9	
WA	2192			(MR1)		DIODE A000 OREQIV.
CB	1712			(MR2)		" " " "
WR	6236			(MR3)		" " " "
D	73319			(MR4)		" " " "
DD	11170			(MR5)		" " " "
DE	6040			(MR6)		" " " "
J	2182			(MR7)		" " " "
DA	72315			C1	102C	
DB	16053			C2	102C	
				C3	101	
				C4	102C	
				TI		TRANSFORMER L950785 OREQIV
				RBI	N°1	BARRETTIER

NOTES - A SPECIAL FACTORS OF SAFETY B SPECIAL ADJUSTMENTS C CIRCUIT POINTS OR MODIFICATIONS

LAYOUT

PLATE A UPPER.
 A B CD WS CB R1 R7 D DE DA + TJA
 RBI BB NU WA WR R4/5/6 DD J DB

PLATE B LOWER.
 MH HJ RT PR CA TM TI C2 C4 + STRIP CONN. (SC) N°121 MOUNTED AT THE REAR.
 + + + + + CI C3 + TJB

(MR1) to (MR7) INCLUDED IN WIRING.

MOD. A GIVES DETAILS OF INTERIM MODIFICATIONS (NZPO) PENDING FINALISATION WITH THE B.C.C OF GBW16671.

APP RC 7.1.69 ISSUE A	ORIGINATED BY	A.T.&E.C°
	DATE	18-1-66
	SIGNED FOR COMMITTEE	HB

RELAY CODES & COMPONENTS LIST, GBW 16671 MOD.A
 UAX NZ 13 OUTGOING JUNCTION TERMINAL UAX
 TO PARENT EXCHANGE

RELAY	BCC CODE	DIAG. FIG.	NOTES	COMP DESIGNATION	BPO CODE	NOTES
MH	72709					
HJ	74601					
RT	16054					
PR	6066					
TM	1744					

NOTES: - A SPECIAL FACTORS OF SAFETY B SPECIAL ADJUSTMENTS C CIRCUIT POINTS OR MODIFICATIONS LAYOUT

MOD A GIVES DETAILS OF INTERIM MODIFICATIONS (N.Z.P.O) PENDING FINALISATION WITH THE B.C.C. OF GBW 16671

1555UEA 7.169 RC	ORIGINATED BY	A.T.R.E.C.
	DATE	18-1-66
	SIGNED FOR COMMITTEE	AB

5 Centimetres
10
15
20
25
30