


RELAY CODES & COMPONENTS LIST, **GBW 16671**
UAX NZ 13 OUTGOING JUNCTION TERMINAL U.A.X.
TO PARENT EXCHANGE.

RELAY	BCC CODE	DIAG. FIG.	NOTES	COMP. DESIGNATION	BPO CODE	NOTES
A	HSD702			R1	N°9	
B	16056			(R2)		1/2 W. 10%
CD	74599			(R3)	N°6	
CA	16485			R4	N°9	
BB	5001			R5	N°9	
NU	15655			R6	N°9	
WS	1941			R7	N°9	
WA	2192			MR107		DIODE DA000 OR EQUIV.
CB	1712			MR889		" " " "
WR	6236			MR10*		DIODE BY133 OR EQUIV.
D	73319			C1	102C	
DD	11170			C2	102C	
DE	6040			C3	101	
J	2182			C4	102C	
DA	72315			TI		TRANSFORMER 950785 OR EQUIV.
DB	16053			RBI	N°1	BALRETTER.

NOTES: - A SPECIAL FACTORS OF SAFETY. B SPECIAL ADJUSTMENTS. C CIRCUIT POINTS OR MODIFICATIONS

LAYOUT



MR10 TO MR7 INCLUDED IN WIRING.
 * MR10 WIRED ACROSS RELAY DE COIL

APP	ISSUE 4 19-3-69	ISSUE 5 3-37-69	ISSUE 6 2-573	ORIGINATED BY	A.T.&E.CO.
REDRAWN.	CA RELAY WAS 12578 MR8&9 ADDED (8264)	DIODE MR10 ADDED (2254)	155.5A 13-12-72 COY. ADDED DIODE MR10 (99606)	DATE	19-3-69
				SIGNED FOR COMMITTEE	<i>[Signature]</i>

NZ.P.O. (86077) 27-8-69

RELAY CODES & COMPONENTS LIST, GBW 16671
UAX NZ 13 OUTGOING JUNCTION TERMINAL UAX
TO PARENT EXCHANGE.

RELAY	B.C.C. CODE	DIAG. FIG.	NOTES	COMPT. DESIGNATION	B.P.O. CODE	NOTES
MH	72709					
HJ	74601					
RT	16054					
PR	6066					
TM	1744					

NOTES:- A SPECIAL FACTORS OF SAFETY B SPECIAL ADJUSTMENTS C CIRCUIT POINTS OR MODIFICATIONS

LAYOUT

APP	RC	R.C.	DLM	JHE	ORIGINATED BY	A.T.&E.C.
ISSUE	ISSUE 4-19-3-69	ISSUE 5 3-37 1. SHT. 1 AMD. ONLY (2254)	ISS. 5A 13-12-72 ADVANCE IN ISSUE ONLY NO AMD. (99606)	ISSUE 6 2-5-73	DATE	19-3-69
REAPPROVED	REAPPROVED				SIGNED FOR COMMITTEE	HP.
					NZ.P.O. (86077) 27-8-69	

5 Centimetres 10 15 20 25 30