


RELAY CODES & COMPONENTS LIST, **GBW 16720**  
 TEST CIRCUIT FOR I.V.F. LINE CIRCUITS  
 N.Z.S.S. A.C. N<sup>o</sup>s 2T&3T

RELAY	B.C.C. CODE	DIAG. FIG.	NOTES	COMPT. DESIGNATION	BPO CODE	NOTES
LR	2079	1			FIG. 1.	
SS	61231	1		MRI-2	DA000 OR EQUIV.	MTD. ON SCA
SR	70477	1	SPRING 21 SPARE & UNWIRED	RI	9A	
SZ	50187	1		CI	MC 103C MK2	
				TDTI	DELAY	A.E.I. UNIT CODE:-
					TIMER GBW16730	UNIT ELECTRONIC 22A
				SCA	STRIP CONN. 145	
					FIG. 2	
DA	6113	2		MRI&2	DA000 OR EQUIV.	MTD. ON SCB
I	2012	2	RETARD	RI&2	40	
RA	6485	2	"	CI&2	102C	
				KC	68	
				ADA	21	DIAL SWITCH WITH NUMBER RING SUITABLE FOR N.Z.P.O. CI
				SCB	STRIP CONN. 145	
				TJA	JACK TEST 30A MK2	
				TJB	" " "	
				R3		820-Ω RADIO TYPE STOCKLIST ER424
				D1		ZENER DIODE B5Y88 STOCKLIST CC919

NOTES:- A.SPECIAL FACTORS OF SAFETY.B.SPECIAL ADJUSTMENTS.C.CCT. POINTS OR MODIFICATIONS:

CI DIAL ADA IS MOUNTED ON RIGHT HAND UPRIGHT LAYOUT. ONE PER TWO RACKS.



ISSUE 1 7.9.64 TDTI WAS TSDTI	ISSUE 2 20-10-64 RI WAS TYPE 9	ISSUE 3 22-3-65 REL. POSNS. ON TESTLINE CCT. AMENDED RI&CI INTER- CHANGED. TITLE & NOTE CI AMENDED (53407)	ISSUE 4 9.3.66 MR3 & MR4 DELETED. (12893)	ISSUE 5 14.4.67	ISSUE 6 RA CHANGED R3 & D1 ADDED ISS. 5A (43295) 27-5-77	ISSUE 7 RED	N.Z.P.O. 21.6.65(94296) B.C.	ORIGINATED BY A.E.I.	DATE 7/9/64	SIGNED FOR COMMITTEE ASH
--	--------------------------------------	---	--	--------------------	--	----------------	------------------------------------	----------------------------	----------------	--------------------------------