

RELAY CODES & COMPONENTS LIST GBW 17120  
 AUTO TELEX SYSTEM  
 DELAYED ALARM & INTERRUPTED ETH. DISTRIBUTION.

RELAY	BCC CODE	DIAG. FIG.	NOTES	COMPT. DESIGN	B.P.O. CODE	NOTES
PR	72920P	1		CI	N° 101	} FIG 1
PS	6119	1		RI	6	
PSA	4365	1		TJ	1A	
ST	4073	1		DS	2/33AN	
AA	6500	2		PLUG	3201	} FIG 2
AB	6500	2		TJ	1A	
BA	7381	2		KAB	6B	
BB	7381	2		CI	103C	
CA	74628	2		RI	6	
CB	74628	2				
STB	72920P	2				
STA	72920P	2				

NOTES - A SPECIAL FACTORS OF SAFETY      B SPECIAL ADJUSTMENTS      C CCT POINTS OR MODIFICATIONS

LAYOUT

FIG. 1





FIG. 2

STB	AB	BB	CB
STA	AA	BA	CA

CI+RI
-------

N.Z. P.O. (54508) 10-10-62. 3-6.

ISSUE  
1. 25-7-62  
CI+RI FIG 2  
ADDED (122102)  
2. 11-9-73  
DLM

ORIGINATED BY	ET
DATE	25-7-62
SIGNED FOR COMMITTEE	<i>[Signature]</i>