



NOTES

- 1 - - - - INDICATES LINE CONNECTED TO MAIN EXCHANGE DURING MAINS FAILURE CONDITIONS
- 2 GBW NUMBERS SHOWN IN BRACKETS REFER TO EQUIPMENTS MANUFACTURED, TO SPECIFICATIONS OS 1035 & OS 105B
- 3 TRUNKING TO BE ARRANGED SO THAT ACCESS TO THE ROUTE REQUIRING THE HIGHER NUMBER OF EXCHANGE LINE CCTS IS OBTAINED BY DIALLING 1
- 4 DIAL 2 ACCESS DURING OPERATOR ATTENDED HOURS ONLY CONNS. SHOWN -x-x- APPLY
- 5 * INDICATES THAT NO 'MOD' VERSION HAS BEEN ISSUED IN THESE CASES THE UNMODIFIED VERSION APPLIES

	EXCHANGE LINE CCT GBW 14690 (GBW 13220)	EXTENSION LINE CCT GBW 13210	MISC CCTS GBW 14720 (GBW 13270)	CONN CCT GBW 14650 (GBW 13160)	RACK COMMON SERVICES GBW 13280	PULSE CIRCUIT GBW 14710 (GBW 13260)		
AUXILIARY SERVICES REQ								
CONNECTION TO MAGNETO MAIN EXCHANGE	GBW - MOD A GBU - * CRD - SEE 15	*	*	*	*	*		
CONNECTION TO WE DROP MAIN EXCHANGE	GBW - MOD B GBU } CRB } SEE 15	*	*	*	SEE 15	*		
CONNECTION TO L M ERICSSON EXCHANGE	GBW - MOD C GBU - * CRD - SEE 15	*	*	*	*	*		
ACCESS TO THREE GROUPS OF EXCHANGE LINES	GBW - MOD D GBU } * CRD } *	GBW - MOD A CRD - *	GBW - MOD A CRD - SEE 15	GBW - MOD A GBU } * CRD } *	*	*		
CODE CALL CIRCUIT GBW 14550 MOD A	GBW - MOD D GBU - MOD D CRD *	GBW - MOD A CRD - *	GBW - MOD A CRD - SEE 15	GBW - MOD A GBU } * CRD } *	GBW - MOD A	GBW MOD A GBU - MOD A CRD - *		

RETRACED FROM ISSC OF 5762 (157698) (8257)				D 23-87	F.J.M.	TRUNKING DIAGRAM 20 LINE PABX WITH AUXILIARY SERVICES	
AMENDMENT PARTICULARS				ISSUE DATE	APPD	A2	
NZPO				40	DRAWN TBS	CHECKED 45	WIRING CIRCUIT
				50	GBW 13150 MOD. A		55

5 Centimetres

0 10 15 20 25 30 35