



NOTES

- 1 - - - - INDICATES LINE CONNECTED TO MAIN EXCHANGE DURING MAINS FAILURE CONDITIONS
- 2 LEVEL 4 WIRED ON 49 LINE PABX ONLY
- 3 GBW NUMBERS SHOWN IN BRACKETS REFER TO EQUIPMENTS OS 1035 & OS 1058
- 4 TRUNKING TO BE ARRANGED SO THAT ACCESS TO THE ROUTE REQUIRING THE HIGHER NUMBER OF EXCHANGE LINE CIRCUITS IS OBTAINED BY DIALLING '1'
- 5 DIAL 2 ACCESS DURING OPERATOR ATTENDED HOURS ONLY CONNS SHOWN -X-X- APPLY

(NOTE 5)

				TRUNKING DIAGRAM 35/49 LINE PABX WITH AUXILIARY SERVICES			
RETRACED	(157699)	D	28-8-78	GHB			
NOTE 5 AND ASSOCIATED CONNS ADD	(33486)	C	5-7-62	CNC			
AMENDMENT PARTICULARS	ISSUE DATE	APP	SHEET 1 OF 2	SIZE A3			W
				GBW 13180 MOD A			
20 NZ PO	25	DRAWN	CHECKED	WIRING	CIRCUIT	30	35

