




AS SEEN FROM REAR

NOTE 1



**NOTES**

- 1- U9 & U11 MAKE CONTACT WHEN RELAY SET IS REMOVED
- 2- / WIRE UNLESS OTHERWISE STATED TO BE 20 SWG.

				<p style="text-align: center;"><b>CHANGED NUMBER MANUAL BOARD RELAY SET 2000 TYPE.</b></p>		
<p>L.D.F CONNECTIONS FOR INCOMING LEADS AMENDED. (31481)</p>						2
<p>AMENDMENT PARTICULARS</p>				ISSUE	DATE	APPD
<p>N.Z.P.O.</p>				<p>50V C</p>		<p>GBU 12140</p>