


AS SEEN FROM REAR

NOTES 1, 3 & 4

NOTE 1



NOTES:-

1. JACK POINTS U9&U11 AND U14&U16 TO MAKE CONTACT WHEN RELAY SET IS REMOVED.
2. ALL WIRING TO BE 20 SWG UNLESS OTHERWISE SPECIFIED
3. STRAP SHELF JACK POINTS U9 & U11 WHEN CIRCUIT IS ASSOCIATED WITH UNDER 3db UNREPEATED LINE.
4. WHEN TERMINATING JUNCTIONS INCOMING FROM MINOR MANUAL EXCHANGES THROUGH SIGNALLING IS NOT REQD ADD STRAP o—o— & DISCONNECT ARTH ON U3

(SHELVES A&B-R-O
 " C&D-R-G
 " E&F-R-BN
 " G&H-R-S
 " J&K-R-B-W

NOTE 4 & ASSOC. STRAPPING WAS NOT SHOWN (68412)				5.	14.1.57	CLM	SLEEVE CONTROL SYSTEM BOTHWAY TRUNK DIFFERENTIAL SIGNALLING (2000 TYPE)
NOTE 3 & ASSOC. STRAP WAS NOT SHOWN U7 WAS SPARE (34813)				4.	26.6.55	CLM	
SHELF STRAP U11 - U19 WAS SHOWN, U19 - U23 MODIFIED. (34843)				3.	25.5.55		
SHELF JACK POINT 'U18' WAS SPARE (30443)				2.	23.6.54	CLM	
(31559)				1.	5.5.54	CLM	
AMENDMENT PARTICULARS				ISSUE	DATE	APP?	REC. -
N.Z.P.O.				DRAWN	CHECKED	WIRING	CIRCUIT
				CLM	EJO 9/10	EJO	
				GBU 13040			50%

5 Centimetres

15

20

25

30