


AS SEEN FROM REAR



**NOTES**

- 1 SHELF JACK U POINTS 9 & 11 MAKE CONTACT WHEN RELAY SET IS REMOVED.
- 2 WHEN EXCHANGE IS EQUIPPED WITH SINGLE LINE CIRCUIT TWO PARTY GROUPS WITHOUT METER DISCRIMINATION 'CONNECT STRAP S' IN ———— AND ADD STRAPS SHOWN —X—X—
- 3 ALL WIRING NOT OTHERWISE SPECIFIED TO BE 22 S.W.G.

REFERENCE TO IDF (MULT.) ADDED (70510)	5	5-4-62	DBH	REVERTIVE RINGING RELAY SET FOR SHARED SERVICE SUBSCRIBERS AND FAULTSMEN 50V C
DELAY ST. S & Z CHANGED TO 3 MINS. (48648)	4	19-12-61	DBH	
ACCESS TO TRAFFIC RECORDER ADDED (11020)	3	21-11-57	DBH	
REFERENCE TO T.C.F. ADDED (65361)	2	15-8-55	CM	
(31002)	1	26-11-54	CM	
AMENDMENT PARTICULARS	ISSUE	DATE	APPD	
N.Z.P.O.	A.M.			GBU 13830

0  
5 Centimetres  
10  
15  
20  
25  
30