

TO NZ 21219  
FIG. 3

- NOTES:-
1. FUSE - 1.5A PER 10 POSITIONS PER DISTRIBUTOR CIRCUIT.
  2. ALL WIRING TO BE 25 SWG UNLESS OTHERWISE SPECIFIED.
  3. FOR WIRING SEE GBW 10690 OR EQUIV.




FIG.3  
M.A.R.

RELEASE (KR)	STEP (KS)	TXM. TEST (KTT)
2	2	2
PRIVATE CONTROL (KPC)	HOLD & TEST (KHT)	
2	4	

TEST DESK LINES TO TEST SELECTOR			
O/G TO 7D ROTARY EXCHANGE			
AMENDMENT PARTICULARS	ISSUE DATE	APP. REF.	PS. 35/53
N.Z.P.O. CE 93/3/53	DRAWN CHECKED	WIRING	CIRCUIT
			GBW 11431 MOD. A.