



TO SPECIAL SERVICE LINE VIA M.D.F. ALSO VIA T.J.F. WHEN REQD NOTE 5

TO T.J.F. WHEN REQD NOTE 5

- N.Z. NOTES:
- A. WHEN USED WITH SOME PHONOGRAM CIRCUITS, SPRINGS J25 & J26 ARE INSULATED.
 - B. WHEN LOCAL METERING IS NOT REQUIRED INSERT STRAP. — | — | —

- NOTES:-
1. FUSING:- 1.5A PER CIRCUIT
 2. U9 & U11 TO MAKE CONTACT WHEN RELAY SET IS REMOVED.
 3. ON SOME EQUIPMENT BRA3 & BRA1 ARE NOT CONNECTED TO "U" POINTS.
 4. Ø FOR WIRING SEE G.B.W. 10640 OR EQUIV.
 5. WHEN CONNECTION TO LINE VIA T.J.F. IS REQD USE CONNECTION SHOWN — | — | — IN ADDITION TO + & -.
 6. ON SOME EARLY EQUIPMENT COLOUR OF NEG. BATT. WIRING WAS BK OR W; POS. BATT. WAS R-B

NOTE 6

BATT; FUSE V (3B) UI2

EARTH ETH. R (3A) UI1

BAR 0.7mm

BATT. V UI2- Lc- DDe- BRA2- Jc- Bc- YC2 (MRA2)

EARTH. R. UI1- Lb- LI- DD4 C MRA1- J5- D2- B21- BRA4- T1

POS. BATT. Y UI5- YA2

SUPERSEDED BY GBW 16810



**SPECIAL SERVICES RELAY SET
POSITIVE BATTERY METERING
2000 TYPE**

RETRACED & METRICATED	157676	5C	1-8-78	RED
N.Z. NOTE B ADDED	34234	5B	8-11-71	BSH
AMENDMENT PARTICULARS	ORDER	ISS	DATE	APPD

SIZE A2 50V C

GBW 11870

T
8

NZPO