


- NOTES:
1. FUSING:- 1.5A PER CIRCUIT.
  2. JACK POINTS 9 AND 11 TO MAKE CONTACT WHEN RELAY SET IS REMOVED.
  3. ALL WIRING TO BE 0.5mm UNLESS OTHERWISE SPECIFIED.
  4. Ø FOR WIRING SEE GBW10640 OR EQUIVALENT.
  5. AT SOME EARLY EXCHANGES THESE LEADS WERE CABLED VIA I.D.F OR T.C.F.

BATTERY BK 0.7mm FUSE 3B U12  
 EARTH R 0.7mm EARTH BAR 3A U11


BATTERY W U12 - R1b - R2b - R3b - R81b - BAa  
 EARTH R U11 - BA2 - OHa - MHa - MHI - B21 - B2 - B5 - CD21 - CD3 - A21 - TRI/E - RB1d - R5a - TJ1.



**AUTO-AUTO RELAY SET  
 SPECIAL SERVICES  
 WITH MANUAL HOLD  
 A.M.X. OR M.A.X.**

50V	E	<input type="checkbox"/>	SLOW RELEASE	<input checked="" type="checkbox"/>	SLOW OPERATE		
A	1.5.80	A.G.	17073		RETRACED & METRICATED		
3	26.4.63		77720		CONTACT BAI CHANGED NOTE 5		
2	3.2.63		14393		& REF. ADD. TITLE AMENDED		
1	3.3.56		66404		REF. TO I.D.F. LOCAL ADD.		
ISS	DATE	DEL	DC	ORDER	CKD	APD	CHANGE
DRN T. EQPT	CKD	ORIGIN T. EQPT.					
TCD A.G.	APPD	STANDARD ATW 22001					
NZPO ENGINEER-IN-CHIEF, WELLINGTON							
	SHT	lof	GBW 14590				
	SIZE	A2					

**PROOF**



UD 236