


NOTES:-

1.1 LOCAL CONDITIONS MAY REQUIRE THESE LEADS TO BE CABLED DIRECT TO M.D.F.

FIG. 1.
REMOTE CALLING EQUIPMENT.

				CHANGED NUMBER MANUAL BOARD RELAY SET 2000 TYPE.			
CON. KEY DELETED DIR. SER. DESK WAS INFM DESK (66433)				2	1-3-63	DBH	
(31481)				1	4-5-45	CM	
AMENDMENT PARTICULARS				ISSUE	DATE	APPD	C
N.P.Z.O.				RWE HF	<i>[Signature]</i>	GBX 12140	SHEET 1-2



NOTE 2.1

NOTES.
2.1 LOCAL CONDITIONS MAY REQUIRE THESE LEADS TO BE CABLED OR WIRED DIRECT TO CALLING EQUIPMENT.

FIG. 2.
LOCAL CALLING EQUIPMENT.

				CHANGED NUMBER MANUAL BOARD RELAY SET 2000 TYPE		
CONCN. KEY DELETED. DIR. SER. DESK WAS INFN. DESK. (6642)				2	1-3-63	DBM
(3148)				1	4-5-54	WV
AMENDMENT PARTICULARS				ISSUE	DATE	APPR
G.P.O. APPROVED AS STANDARD						
N.Z.P.O.						
RWE						
W. G. King						
1-12-54						
				GBX 12140		
				SHEET 2-2		