



RELAY CODES & COMPONENTS LIST GBW 10591

TEST RACK, TEST JACK, SPEAK JACK
CONNECTING & TELEPHONE CIRCUITS

RELAY	BCC CODE	DIAG FIG.	NOTES	COMPT. DESIGN	B.P.O. CODE	NOTES
D	40523	1		IC	3/16	
DK	2001	1		TI	3/43A	
PR	2012	1		C1,2,3	103 C	
PR	B76984	1	NZ NOTE A	C4+R10	102C + N° 6	
IC	5318	1		C5	115	
SW	4864P	1		C6	101	
				MR1	2/2AZ	
				MR2	1/12AZ	
				MR3,MR4		DA000 OR EQUIV.
				R1,2,3,4	N° 9	
				R5,6	N° 35B	
SD	7131	2		R7	N° 15A	
				R8, R9	N° 9	
				R11,12,13,14	N° 9	
IA	6137	3		RBI	N° 1	
				VMI	N° 36 B MOD.	
				KN+KE	212	
				KK+KL	212	
SX	6008	6		KC0+KR	208	
				KZ+KS	208	
				KX+KD	174	
				KP+KCS	174	
				KH+KB	301	
				KV+KVR	198	
				KWR	72	
				KSA	72	
				KCA	72	

NOTES - A SPECIAL FACTORS OF SAFETY. B SPECIAL ADJUSTMENTS. C CCT POINTS OR MODIFICATIONS.

LAYOUT



NZ NOTE

A. PR RETARD COIL REPLACE WITH RELAY CODE B76984 AS REQUIRED.

Centimetres

5

10

15

20

25

30

ISSUE	8-5-64	RGN
NZ NOTE ADDED(55997)		
IA	20-8-76	

ORIGINATED BY	ET
DATE	8-5-64
SIGNED FOR COMMITTEE	<i>[Signature]</i>

10-7-64 AS

RELAY CODES & COMPONENTS LIST GBW 10591

TEST RACK, TEST JACK, SPEAK JACK,
CONNECTING & TELEPHONE CIRCUITS.

RELAY	BCC CODE	DIAG. FIG.	NOTES	COMP. DESIGN	B.P.O. CODE	NOTES
				KIW	291	
				KIS	291	
				KIC	291	
				KJ	68	
				KM+KG	219	
				KDA+KDC	264	
				KS	68	
				KRA+KRC	216	
				KF	279	
				KCR	289	

NOTES - A SPECIAL FACTORS OF SAFETY. B SPECIAL ADJUSTMENTS. C CCT POINTS OR MODIFICATIONS LAYOUT

5 Centimetres
10
15
20
25
30
O.P.Z.N.

ISSUE 8-5-64
NO CHANGE
SHT I AMD
(55997)
IA 20-8-76

ORIGINATED BY	ET
DATE	8-5-64
SIGNED FOR COMMITTEE	