


RELAY CODES & COMPONENTS LIST, **GBW 11680**
OUTGOING I.V.E. LINE CIRCUIT FOR BOTHWAY WORKING


| RELAY | B.C.C. CODE | DIAG. FIG. | NOTES | COMPT. DESIGNATION | BPO CODE | NOTES |
|-------|-------------|------------|-----------------------|--------------------|------------------|--------------------------|
| A | HSD702 | | TEST & R.A. FIGURES B | R1-7 | 9 | |
| AA | HSD701 | | TEST & R.A. FIGURES B | R8 | 6 | |
| B | 5890 | | | R9-11 | 15 | |
| BB | 5891 | | | R12 | 12 | |
| CD | 5892 | | | R13 | 9 | |
| CF | 5893 | | | C1 | 102 | |
| CR | 5923P | | | C2 | 101 | |
| D | 5825 | | | MRI | 1/12A | |
| DB | 5894 | | | T | 415A | .E.I. CODE |
| DD | 5888 | | | VU1 | 1001 | VALVE UNIT (A.E.I. CODE) |
| SA | 5941P | | | RX1-5 | NON LINEAR NO. 2 | MTD. IN WIRING |
| SB | 5895 | | | | | |
| SP | HSD513 | | TEST & R.A. FIGURES B | | | |
| SR | 5942 | | | | | |
| RG | 60456 | | | | | |

NOTES:-A. SPECIAL FACTORS OF SAFETY. B. SPECIAL ADJUSTMENTS. C. COT. POINTS OR MODIFICATIONS.

FRONT VIEW LAYOUT



REAR VIEW (BOXES & COVERS OPEN)



N.Z.P.O.
(58095) 12-1-67.

ISSUE 1
11-7-66
PC RELAY
DELETED(68182)
ISSUE 2
9-11-66

ORIGINATED BY A.E.I.
DATE 11-7-66
SIGNED FOR COMMITTEE ASH