


FINAL SELECTOR FOR MULTI-PARTY LINE

RELAY	BCC CODE	DIAG. FIG	NOTES	COMP. DESIGNATION	BPO CODE	NOTES
A	1299A			R1	Nº 9	RESISTOR 150 ^Ω
AC	20801P			R2	Nº 9	RESISTOR 200 ^Ω
				R3	Nº 9	RESISTOR 200 ^Ω
				R4	Nº 9	RESISTOR 60 ^Ω
				R5	Nº 9	RESISTOR 500 ^Ω
B	20786P			R6	Nº 9	RESISTOR 500 ^Ω
CD	21903			R7	Nº 9	RESISTOR 1K ^Ω
CA	20788					
DE	HSD502			MR1	2AZ	RECT ER
				MR2	1/12AZ	RECTIFIER
DA	20789			MR3	1/12AZ	RECTIFIER
				MR4	1/12AZ	RECTIFIER
DB	20790					
E	20802			C1	MC102	CAPACITOR
				C2	MC102	CAPACITOR
FD	7794					
H	20791				Nº 21E	TEST JACK
HR	20771			Ø	1/55H/1	RELAY SHIELD
				*	1/56U/54	RELAY GUARD
OC	2518					
PM	1007			TR1	G.E.C.DR6.P97127	TRANSFORMER
				D1, D2		1N4007 OR EQUIV.
TL	20812					
TM	20797					


NOTES A SPECIAL FACTORS OF SAFETY B SPECIAL ADJUSTMENT C CCT POINTS OF MODIFICATIONS.

LAYOUT

TOP REAR COVER



CAPACITOR BOX



TRI	R1/ R2/ R3
	B
Ø A	CD
OC	CA *
DE	DR
F	DA
* DB	H
HR	W
X	Y
Z	FD
AC	PM
* TL	E *
TM	+

N.Z.P.O (56857) 9-3-62 PAC

ISSUE 1
24-10-61
AWAS 21869P
(72879)

ISSUE 2
16-3-64
NZM-TX
(193688)

JR
28-7-80
155.2A

ORIGINATED BY G.E.C.

DATE 24-10-61

SIGNED FOR COMMITTEE *[Signature]*

5 Centimetres 10

15

20

25

30

FINAL SELECTOR FOR MULTI-PARTY LINE

RELAY	BCC CODE	DIAG. FIG	NOTES	COMPT. DESIGNATION	BPO CODE	NOTES
W	20799					
X	20800					
Y	20800					
Z	1007					
F	HSD502					
DR	71552					

NOTES - A SPECIAL FACTORS OF SAFETY B SPECIAL ADJUSTMENTS C C.T. POINTS OF MODIFICATIONS.

LAYOUT

Centimetres
5
10
15
20
25
30

N.Z. P.O (56857) 9-3-62. PRC

<p>ISSUE 1 24-10-61 ISSUE ADVANCED ONLY (72879)</p>	<p>ISSUE 2 16-3-64. NO CHANGE ISS. ADV. (193688)</p>	<p>JR 28.7.80 ISS. 2A.</p>	<p>ORIGINATED BY G.E.C.</p>
			<p>DATE 24-10-61</p>
			<p>SIGNED FOR COMMITTEE </p>