



RELAY CODES & COMPONENTS LIST, GBW 14170 MOD.A
 INTER-SWITCHBOARD LINE CCT. (B/W AUTO-AUTO LOOP DIALLING)
 50/1200 LINE P.A.B.X. TO SATELLITE PABX.

RELAY	BCC CODE	DIA FIG	NOTES	COMPT DESIGNATION	BPO CODE	NOTES
AA	H5521		B	TRI	BM 4177/2	S.T.C. CODE
AB	H5517		B	C1	MC 102C	
B	1751			C2	MC 102C	
CR	60642			C3	MC 102C	
DD	4070			C4	MC 101	
DL	71773			C5	MC 101	
DR	70150			C6	MC 101	
DC	5778			MR1		
BR	1618			MR2	D18-G-1W SEL	S.T.C. CODE
OG	6381			MR3		
S	60637		B	MR4		
SR	4046			MR5	2/GA	OR SELENIUM EQUIV
LD	H5518		B	R1	NO. 6	MTD ON CA
Z	4250			R2	NO. 6	MTD ON CI
ZR	2782			R3	NO. 9	
LS	HSD 233		B	R4	NO. 9	
SRA	6001		EARLIER CCTS. USED B5246	R5	NO. 9	
DB	50007BB		EARLIER CCTS USED B7449	R6	NO. 9	
				R7	NO. 9	
				R8	NO. 9	
				R9	NO. 9	
				R10	NO. 9	
				R11	NO. 9	
				R12	NO. 12	
				R13	NO. 12	
				D1-5	DIODE	1N4003 S/L N° K905

LAYOUT




NOTES

- A. SPECIAL FACTORS OF SAFETY
- B. SPECIAL ADJUSTMENTS
- C. CCT. POINTS & MODIFICATIONS



TOP REAR COVER

MIDDLE REAR COVER



FRONT VIEW

≠ RELAY GUARD

SCA (MTD REAR RELAY DB) CAPACITOR BOX

N.Z.P.O. (16089) 24-870 (A) B.

ISSUE 1 2011/01/01 WAS C. & D. S.	RELAY OP DELETED (22118)	ISS A 231073 DIODE D 1 ADDED. (129467) 5AW	ISS B 25-10-77 REL D.C. WAS D. MR13 A DELETED D2-15 ADDED. SCA RE-DRAWN. (63329)	ISS C 24.9.80	ORIGINATED BY	S.T.C.
					DATE	20.1.60
					SIGNED FOR COMMITTEE	R.E.D.