

RELAY CODES & COMPONENTS LIST, GBW 16500



PARENT EXCHANGE 1/C LINE CIRCUIT FROM DEPENDENT EXCHANGE

N.Z.S.S.A.C. No. 3T

RELAY	B.C.C. CODE	DIAG. FIG.	NOTES	COMPT. DESIGNATION	BPO CODE	NOTES
A	5897 P	B		R1	15A	NON-INDUCTIVE (NOTUSED)
AK	5943 P			R4-8	9	
AX	HSD 511	B		R9&10	6	
B	5944			R11	12	
BB	5945			R12	40	
BR	5946			R2-3	15	NON-INDUCTIVE
CD	50113			R11-15	RADIO TYPE	MTD IN WIRING
D	5936			MRI-5	DA 000	JOSEPH LUCAS CODE MTD IN WIRING
DA	5901			R.X.1-8	?	MTD. IN WIRING
DB	4088			T1	415A	A.E.I. CODE
DR	5902 P			T2	444A	A.E.I. CODE
DY	1105			C1	102C	
DZ	5948			C2&3	101	
MB	10730			C4&5	8017 B	MTD ON SCA-SCB-SCC
MH	4320			TAR.1	TRANSISTOR REC'VR	A.E.I. UNIT. CODE :-
RL	72399				GBW 16560	P.W.U. 45C (MULLARD CODES)
				SCA-SCC	MINIATURE MTG STRIP	CARR FASTENER CODE-
				TAG PLATES	CINCH TYPE 2dOd	A.E.I. DRG :- DS 4125 GRP 2
				URI	RES. ASSEM. 1077	A.E.I. CODE

NOTES:- A. SPECIAL FACTORS OF SAFETY. B. SPECIAL ADJUSTMENTS. C. CCT. POINTS OR MODIFICATIONS.

LAYOUT.



+ COVER P.O. DWG NO. S.S.H/1
 Ø GUARD 1.
 1 PLUG 32 P. P.O. 3205
 1 P.O. JACK TEST 21E MK 2
 1 P.O. JACK TEST 21F MK 2
 1 LINK P.O. 'N' RED

FRONT VIEW.

REAR VIEW

ISSUE 1 19.3.65 LINK P.O. 'N' RED WAS LINK P.O. 'N' RED	ISSUE 2 17.5.65 RELAYS RLA & TW TRANSPOSED CAPACITOR BOX LAYOUT AND TITLE AMENDED	ISSUE 3 17.9.65 HINGE POSITIONS ADDED STRIP CONNS IN RECEIVER BOX INTERCHANGED	ISSUE 4 10.1.66 RXG-8 ADDED (83760)	ISSUE 5 22.5.67 R11-15 ADDED R1 DELETED FROM WIRING (193356) 155.5A 2.5.78	N.Z.P.O. (58054) 2.12.66	ORIGINATED BY A.E.I.
					DATE 19.3.65	SIGNED FOR COMMITTEE A.S.H. 19/3/65

5 Centimetres

10

15

20

25

30

