



GBW 16900

RELAY CODES & COMPONENTS LIST

UAX NZ13/CCB LINE ROUTE RESTRICTION CCT W/ DISCRIMINATING FACILITIES
(PULSE GENERATION TYPE)

RELAY	ECC CODE	DIAG. FIG	NOTES	COMPT. DESIGNATION	BPO CODE	NOTES
LA	22434	1	B	R2,R3,R4	N° 40-200 Ω	
B	1438IP	1		R.1	N° 40-820 Ω	
BB	2378	1		SCA	121B	
CA	22601	1		SCB	145 DN	
CD	22522	1		SCC	176A	
DSA	1717	1		DS	4/31A WITH JACK 89A	
DSB	1108	1		EIA, CIB, C2	N° 8017A 2:2MF	
H	22577	1		C3, C6, C7	N° 8017A 1MF	
I	1523	1		C4, C8	N° 8017A 0.47MF	
IPD	72828	1		C5	N° 8017A 0.22MF	
NRD	50095	1		DI	CV 7028	
NU	22650 ^x _{PU}	1		D2, TO, D10	CV 8308	D9 & D10 IN WIRING
PU	5616P	1	B	D11, D12	CV 7030 OR EQUIV	
RDO	4027	1		RX1, RX2, RX3	N° 2.	
RR	RR2038	1	B	KEY	2101	
GS	73076	1		MOUNTING	N° P.O. CODE	G.E.C-AEI DT 25035 ATTACHED TO MFG. F151/20AH BY 2 - 0.0A HEX HD SCREWS SUPPLIED.

NOTES A SPECIAL FACTORS OF SAFETY B SPECIAL ADJUSTMENTS C CCT POINTS OF MODIFICATIONS



5 Centimetres 10

15

20

25

30

N.Z.P.O. R.C.
(13684) 5-6-70

RR WAS 2041 KA REMOVED
ISSUE 1 8-5-68
BB WAS 22600
ISSUE 3 6-10-68
MOUNTING & KEY WAS MGT. SHAWN
7-2-68 ISSUED
R1 WAS 200 Ω R4 WAS 820 Ω
9-5-69 ISS. 5
NU WAS 22602
TITLE AMENDED R.C.
11-7-69 ISS. 6
D11 & D12 ADD (129477)
1957 16-10-77 DWH

ORIGINATED BY G E C^{NZ}
DATE 7. 12. 67
SIGNED FOR COMMITTEE *[Signature]*