



RELAY CODES & COMPONENTS LIST **GBW 17240**
 AUTOMATIC TELEX SYSTEM
 SIGNAL MONITOR RELAY SET.

RELAY	B.C.C. CODE	DIAG. FIG.	NOTES	COMPT. DESIGN	B.P.O. CODE	NOTES
D	TMC4H7			R4	N° 12	
KA	5001B			R6	" 12	
ST	6001B			R7A	" 9	
TA	HS706		BI	R7B	" 9	
				R5	" 16GD	
				C1+R1	N° 100 + N° 6	
				C2+R2	N° 100 + N° 6	
				C3+R3	N° 101 + N° 6	
				A	2/44 AN	
				VI	CV2007	WITH BRACKET MFG. 1/DBR/205 VALVE HOLDER N° 1 & ADAPTER RING.
				TJ	1A	
				R8	15GD	
				R9	15GD	
				SCA	145DN	
				Y1	CV491	VALVEHOLDER N° 38

NOTES - A SPECIAL FACTORS OF SAFETY. B SPECIAL ADJUSTMENTS. C CCT POINTS OR MODIFICATIONS.
 BI TEST & R.A. FIGURES LAYOUT



N.Z.P.O. (54508) 10-10-62 8.6.

ISSUE 1. 15-8-62 R8 & R9 ADDED TO COMPI LIST NOTES CHANGED (77879)
 2. 2-11-62 R5 WAS CARBON N°1 VI WAS CV2007 SCA ADDED (30386)
 3. 28-3-72

ORIGINATED BY **ET**
 DATE **15-8-62**
 SIGNED FOR COMMITTEE *[Signature]*

0
5 Centimetres
10
15
20
25
30