


RELAY CODES & COMPONENTS LIST **GBW 20182**
 DISCRIMINATING SELECTOR REPEATER
 REG. & P/L - 200 OUTLET-2000TYPE-WITH O/F ROUTEING FACILITY

RELAY	BCC CODE	DIAG FIG.	NOTES	COMPT DESIGNATION	BPO CODE	DIAG FIG.	NOTES
A	HSD 702	1A	B	R1	9	1A	SPECIAL-COPPER WINDING
AA	10838P	1A	B	R2	9	1A	
B	4527P	1A		R3	9	1A	
BB	2042A	1A		R4	9	1A	
CD	10708	1A	B	R5	9	1A	
CR	4570	1A		R6	9	1A	
DE	7905	1A		R7	12	1A	
DD	70004	1A		R8	12	1A	
HA	4530	1A		R9	12	1A	
HB	4531	1A		R10	17	1A	
J	4532	1A		R11	6	1A	MOUNTED ON CAPACITOR C4
JG	10535	1A		R12	6	1A	MOUNTED ON CAPACITOR C3
JR	4699	1A		R13	6	1A	MOUNTED ON CAPACITOR C3
K	5720	1A		R14	12	1A	
LD	5753	1A		R15	9	1A	
LS	10284	1A		R16	9	1A	
				R17	RADIO	1A	1/4 W 10%

NOTES A SPECIAL FACTORS OF SAFETY B SPECIAL ADJUSTMENTS C CCT POINTS OR MODIFICATIONS

LAYOUT OF FIGS. 1A



- * FITTED WITH SHIELD SSH/1
- + FITTED WITH GUARD SGU/54
- # WHEN FITTED R B1 MOUNTED IN THIS POSITION WHEN BARRETTOR R B1 IS FAULTY IT IS TO BE REPLACED WITH RESISTOR R15 & R16.

NZPO (99624) 26.3.73

ISS. 1. RELAY DE WAS D (2489)	ISS. 2. 6.7.73	ISS. 3. 15.2.84	ISS. 4. 18.4.84	ISS. 5. 2.8.84
MOD. B.	R17 ADDED (42354)	NO CHANGE SHT. 2 AMD. (42447)	NO CHANGE SHT. 2 AMD. (54280)	

ORIGINATED BY	
DATE	

RELAY CODES & COMPONENTS LIST **GBW 20182**
DISCRIMINATING SELECTOR REPEATER
REG. & P/L - 200 OUTLET-2000 TYPE-WITH O/F ROUTEING FACILITY

RELAY	BCC CODE	DIAG FIG.	NOTES	COMPT DESIG-NATION	BPO CODE	DIAG FIG.	NOTES
LT	10848	1A		RB1	1	1A	RESISTOR BARRETTER
MC	4543	1A		RX1	2	1A	NON-LINEAR RESISTOR MOUNTED ON REAR OF RELAY AA
				RX2	2	1A	NON-LINEAR RESISTOR MOUNTED ON REAR OF RELAY CR
MD	73240	1A		C1	MC 102	1A	
				C2	MC 102	1A	
MH	4573 P	1A		C3	MC 105	1A	
				C4	MC 104	1A	
RS	5754	1A		MR1	1/12A	1A	
RT	2780	1A		MR2	2P/6A	1A	
				MR3	2P/	1A	
SC	10847	1A					
DA	4575	1B		D1		1A	IN 4003 OR EQUIV. MOUNTED IN WIRING, A LEAD ON S2
				D2		1A	IN 4003 OR EQUIV. MOUNTED IN WIRING, A LEAD ON MD22
OA	4538	1B		D3		1A	BZY 886V2 OR EQUIV. MOUNTED ACROSS LD 26 - MH b
				D4		1A	IN 4003 OR EQUIV. MOUNTED IN WIRING, A LEAD ON AA1
DA	4575	1CORID		TRI		1A	TRANSFORMER L 950785 OR EQUIV.
DB	4575	1CORID		D5	DIODE	1A	IN 4007
				D6	DIODE	1A	IN 4007
OA	4540	1CORID					
OB	10704	1CORID					
JA	6008	2C					
JB	10232	2C					

NOTES. **A** SPECIAL FACTORS OF SAFETY **B** SPECIAL ADJUSTMENTS **C** CT. POINTS OR MODIFICATIONS

LAYOUT

FIG. 1B

1R2/2R2/3R2	1R1/2R1/3R1
1DA	1 OA
2DA	2 OA
3DA	3 OA

FIG. 1C

R1/R2	
DA	OA
DB	OB

FIG. 1D

1R2/2R2/3R2	1R1/2R1/3R1
1DA	1DB
1 OA	1 OB
2DA	2DB
2 OA	2 OB
3DA	3DB
3 OA	3 OB

NZPO (99624) 26-3-73

WAS GBW 10422 APP	DLM
MOD. B	
ISSUE 1. SHT. 1 AMD (2489)	
ISS. 2. 6-7-73 DLM	
C5 ADDED (42354)	
ISS. 3. 17-2-84 GCG	
C5 DELETED (42447)	
ISS. 4. 18-4-84 GCG	
D5 & D6 ADDED (54280)	
ISS. 5. 2-8-84 GCG	

ORIGINATED BY

DATE

RELAY CODES & COMPONENTS LIST GBW 20182

DISCRIMINATING SELECTOR REPEATER

REG. & P/L-200 OUTLET-2000 TYPE-WITH O/F ROUTEING FACILITY

RELAY	BCC CODE	DIAG FIG.	NOTES	COMPT DESIGNATION	BPO CODE	DIAG FIG.	NOTES
				R1	12	1B	
				R2	12	1B	
				R1	12	1CORID	
				R2	12	1CORID	

NOTES. **A** SPECIAL FACTORS OF SAFETY **B** SPECIAL ADJUSTMENT **C** LCT POINTS OR MODIFICATIONS

LAYOUT

0
5
10
15
20
25
30

Centimeter

30

NZPO

(39624) 26.3.73

WAS GBW 10422 APP MOD. B.	DIM	ORIGINATED BY	
ISSUE 1. SHT. 1 AMD. (2489)		DATE	
ISS. 2. 6.7.73 DIM NO CHANGE			
ISS. ADV. (42354)			
ISS. 3. 15.2.84 GCG NO CHANGE			
SHT. 2 AMD. (42447)			
ISS. 4. 18.4.84 GCG NO CHANGE			
SHT. 2 AMD. (54280)			
ISS. 5. 2.8.84 GCG			